

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Site: COCKNAGE ROAD (37601017)

Locality: ROUGH CLOSE, STAFFORDSHIRE

Area: S - Stone Rural North

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Driven		Feature Type:	Inspected Network		Area: S - Stone Rural North	
Batch: 1868662 - Inspection Batch			Route: SI_North_Q_08_MEIR HEATH				Date: 23/07/2026	
1551037	Highway Road Marking Repairs - Repaint worn SLOW markings	23/07/2026	18mtrs south of access to Heather Lodge	RMark - Worn	Internal		Committed	2439895
1551021	Highway Carriageway Repairs - T3	23/07/2026	On inside edge of bend by pool.	CW - Pothole	Internal		Committed	2387378
1551032	Highway Carriageway Repairs - T3 Please cut and patch marked area, consisting of potholes and adjacent crazing and cracking.	23/07/2026	Approximately 20 meters east from access to property called Rose Cottage	CW - Pothole	Internal		Committed	2408432
1551035	Highway Carriageway Repairs - Type 2	23/07/2026	5 mtrs before slow marked on road	CW - Pothole	Internal		Committed	2220367
Batch: 1847824 - Inspection Batch			Route: Adhoc/Reactive Inspections				Date: 05/05/2026	
1538318	Pre-Surface Dressing-site 6537 ROADMASTER WORKS AS REQUIRED ROAD CLOSURE USING 15MIN DELAY SIGNS MOBILE WORKS (CW - Crazing/Cracking)	05/05/2026	From A5005 lightwood rd to bend by Heather Lodge	CW - Crazing/Cracking	Internal		Committed	2429446
Batch: 1847385 - Inspection Batch			Route: Adhoc/Reactive Inspections				Date: 30/04/2026	
1538022	Pre-Surface Dressing-site 6537 ROADMASTER WORKS AS REQUIRED ROAD CLOSURE USING 15MIN DELAY SIGNS MOBILE WORKS	30/04/2026	From A5005 lightwood rd to bend by Heather Lodge	CW - Crazing/Cracking	Internal		Committed	2429207
Batch: 1844182 - Inspection Batch			Route: Adhoc/Reactive Inspections				Date: 21/04/2026	
1535888	Highway Carriageway Repairs - T4	21/04/2026	40m past vac to rose cottage on the right	CW - Pothole	Internal		Committed	2427432
Batch: 1844155 - Inspection Batch			Route: SI_North_Q_08_MEIR HEATH				Date: 21/04/2026	
1535864	Highway Carriageway Repairs - T4 Please make good area marked Job 2 of 6	21/04/2026	20m past vac to rose cottage on the right	CW - Pothole	Internal		Committed	2427422
1535874	Highway Carriageway Repairs - T4 Please make good area marked Job 5 of 6	21/04/2026	20m past vac to rose cottage on the right	CW - Pothole	Internal		Committed	2427427
1535873	Highway Carriageway Repairs - T4 Please make good area marked Job 4 of 6	21/04/2026	20m past vac to rose cottage on the right	CW - Pothole	Internal		Committed	2427426
1535861	Highway Carriageway Repairs - T4 Please make good area marked Job 1 of 6	21/04/2026	20m past vac to rose cottage on the right	CW - Pothole	Internal		Committed	2427419
1535869	Highway Carriageway Repairs - T4 Please make good area marked Job 3 of 6	21/04/2026	20m past vac to rose cottage on the right	CW - Pothole	Internal		Committed	2427425
1535876	Highway Carriageway Repairs - T4 Please make good area marked Job 6 of 6	21/04/2026	20m past vac to rose cottage on the right	CW - Pothole	Internal		Committed	2427428

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Driven	Feature Type:	Inspected Network		Area:	S - Stone Rural North
Batch:	1819520 - Inspection Batch			Route:	SI_North_Q_08_MEIR HEATH		Date:	21/01/2026
	No actionable defects found							
Batch:	1808148 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	25/11/2025
1514181	Highway Carriageway Repairs - T4 Please make safe until permanent Repairs will be carried out under job number 2408432	25/11/2025	Approximately 30 meters east from access to property called Rose Cottage	CW - Pothole	Internal		Committed	2408434
Batch:	1808140 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	25/11/2025
1514178	Highway Carriageway Repairs - T3 Please cut and patch marked area, consisting of potholes and adjacent crazing and cracking.	25/11/2025	Approximately 20 meters east from access to property called Rose Cottage	CW - Pothole	Internal		No Action Required	
Batch:	1803013 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	30/10/2025
1511480	Pre-Surface Dressing -6537 2026works patching required	30/10/2025	From A5005 lightwood road to stoke city boundary (bend by Heather Lodge	CW - Crazing/Cracking	Internal		Committed	2406108
Batch:	1800287 - Inspection Batch			Route:	SI_North_Q_08_MEIR HEATH		Date:	20/10/2025
	No actionable defects found							
Batch:	1798352 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	09/10/2025
1509053	Highway Carriageway Repairs - T3 This job supercedes existing job number 2387388	09/10/2025	Approximately 10 meters downhill from the property called Heather Lodge	CW - Pothole	Internal		Committed	2403910
Batch:	1781182 - Inspection Batch			Route:	SI_North_Q_08_MEIR HEATH		Date:	22/07/2025
	No actionable defects found							
Batch:	1760233 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	28/04/2025
1489955	Highway Carriageway Repairs - T3	28/04/2025	On inside of bend just up from access to Heather Lodge. Opposite severe deviation chevron boards.	CW - Pothole	Internal		Committed	2387381
Batch:	1760232 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	28/04/2025
1489952	Highway Carriageway Repairs - T3	28/04/2025	On inside of bend just up from access to Heather Lodge. Opposite severe deviation chevron boards.	CW - Pothole	Internal		No Action Required	
Batch:	1760230 - Inspection Batch			Route:	SI_North_Q_08_MEIR HEATH		Date:	28/04/2025
1489951	Highway Carriageway Repairs - T3	28/04/2025	On inside of bend just up from access to Heather Lodge. Opposite severe deviation chevron boards.	CW - Pothole	Internal		No Action Required	
1489961	Highway Carriageway Repairs - T3 x 5	28/04/2025	On both the upper and lowerside of the access to Heather Lodge.	CW - Pothole	Internal		Committed	2387388
1489960	Highway Road Marking Repairs - SCREED - refresh all give way markings including triangle road marker.	28/04/2025	At jct with Lightwood Road.	RMark - Worn	Internal		Committed	2387389

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Driven	Feature Type:	Inspected Network		Area:	S - Stone Rural North
Batch:	1760226 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	28/04/2025
1489948	Highway Carriageway Repairs - T3	28/04/2025	On inside edge of bend by pool.	CW - Pothole	Internal		No Action Required	
Batch:	1760209 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	28/04/2025
1489939	Highway Signage Repairs - reset leaning post and reattach chevron board back onto posts.	28/04/2025	On outside of bend opposite Pool.	TS - Misaligned/Loose	Internal		Committed	2367364
Batch:	1736841 - Inspection Batch			Route:	SI_North_Q_08_MEIR HEATH		Date:	21/01/2025
	No actionable defects found							
Batch:	1717961 - Inspection Batch			Route:	SI_North_Q_08_MEIR HEATH		Date:	25/10/2024
1465571	Highway Signage Repairs - reset leaning post and reattach chevron board back onto posts.	25/10/2024	On outside of bend opposite Pool.	TS - Misaligned/Loose	Internal		No Action Required	
Batch:	1695653 - Inspection Batch			Route:	SI_North_Q_08_MEIR HEATH		Date:	01/08/2024
1452784	Highway Carriageway Repairs - T4	01/08/2024	20m prior to bridge area	CW - Pothole	Internal		Committed	2356270
Batch:	1681289 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	11/06/2024
1444994	Highway Carriageway Repairs - Type 2	11/06/2024	Opposite access 5 mtrs before double bend sign	CW - Pothole	Internal		Committed	2220368
Batch:	1681264 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	11/06/2024
1444985	Highway Carriageway Repairs - T3. To wet to mark.	11/06/2024	Around gully by culverted water course.	CW - Cracking/Cracking	Internal		Committed	2329906
Batch:	1681261 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	11/06/2024
1444984	Highway Carriageway Repairs - T3. To wet to mark.	11/06/2024	Around gully by culverted water course.	CW - Cracking/Cracking	Internal		No Action Required	
Batch:	1681253 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	11/06/2024
1444979	Highway Carriageway Repairs - T4	11/06/2024	Opposite pond by pull in parking area for Barlaston and Rough Close Common Local Nature Reserve.	CW - Pothole	Internal		Committed	2285634
Batch:	1674168 - Inspection Batch			Route:	SI_North_Q_08_MEIR HEATH		Date:	16/05/2024
	No actionable defects found							
Batch:	1649642 - Inspection Batch			Route:	SI_North_Q_08_MEIR HEATH		Date:	08/02/2024
	No actionable defects found							
Batch:	1641914 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	11/01/2024
1418643	Highway Carriageway Repairs - T3. To wet to mark.	11/01/2024	Around gully by culverted water course.	CW - Cracking/Cracking	Internal		No Action Required	

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Driven	Feature Type:	Inspected Network		Area:	S - Stone Rural North
Batch:	1641913 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	11/01/2024
1418642	Highway Carriageway Repairs - T4 adjacent blocked gulley. Road is being damaged by blocked gulley not draining surface water away. Cones placed to warn/guard. This job supersedes existing job number 2328086.	11/01/2024	Adjacent blocked gulley just before fencing to culverted water course.	CW - Pothole	Internal		Committed	2329904
Batch:	1641911 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	11/01/2024
1418640	Highway Carriageway Repairs - T4	11/01/2024	Just before fencing to culverted water course.	CW - Pothole	Internal		Committed	2329905
1418641	Highway Carriageway Repairs - T4 adjacent blocked gulley. Road is being damaged by blocked gulley not draining surface water away. Cones placed to warn/guard. This job supersedes existing job number 2328086.	11/01/2024	Adjacent blocked gulley just before fencing to culverted water course.	CW - Pothole	Internal		No Action Required	
Batch:	1638491 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	21/12/2023
1416382	Highway Carriageway Repairs - T4 adjacent a flooded gulley.	21/12/2023	Travelling towards Cocknage and located on the left just before the culverted water course.	CW - Pothole	Internal		Committed	2328086
Batch:	1638490 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	21/12/2023
1416381	Highway Carriageway Repairs - T4 adjacent a flooded gulley.	21/12/2023	Travelling towards Cocknage and located on the left just before the culverted water course.	CW - Pothole	Internal		No Action Required	
Batch:	1638489 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	21/12/2023
1416380	Highway Carriageway Repairs - T4 adjacent a flooded gulley.	21/12/2023	Travelling towards Cocknage and located on the left just before the culverted water course.	CW - Pothole	Internal		No Action Required	
Batch:	1638488 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	21/12/2023
1416379	Highway Carriageway Repairs - T4 adjacent a flooded gulley.	21/12/2023	Travelling towards Cocknage and located on the left just before the culverted water course.	CW - Pothole	Internal		No Action Required	
Batch:	1638487 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	21/12/2023
1416378	Highway Carriageway Repairs - T4 adjacent a flooded gulley.	21/12/2023	Travelling towards Cocknage and located on the left just before the culverted water course.	CW - Pothole	Internal		No Action Required	
Batch:	1638486 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	21/12/2023
1416377	Highway Carriageway Repairs - T4 adjacent a flooded gulley.	21/12/2023	Travelling towards Cocknage and located on the left just before the culverted water course.	CW - Pothole	Internal		No Action Required	

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Driven	Feature Type:	Inspected Network		Area:	S - Stone Rural North
Batch:	1637623 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	18/12/2023
1415933	Highway Carriageway Repairs - T4 adjacent a flooded gulley.	18/12/2023	Travelling towards Cocknage and located on the left just before the culverted water course.	CW - Pothole	Internal		No Action Required	
Batch:	1637621 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	18/12/2023
1415931	Highway Carriageway Repairs - T4 adjacent a flooded gulley.	18/12/2023	Travelling towards Cocknage and located on the left just before the culverted water course.	CW - Pothole	Internal		No Action Required	
Batch:	1629408 - Inspection Batch			Route:	SI_North_Q_08_MEIR HEATH		Date:	13/11/2023
	No actionable defects found							
Batch:	1609911 - Inspection Batch			Route:	SI_North_Q_08_MEIR HEATH		Date:	08/08/2023
1402164	Highway Carriageway Repairs - T4 x 1	08/08/2023	Opposite pool approx 311 metres from junction with the A5055 Lightwood Road travelling towards Cocknage from Rough Close.	CW - Pothole	Internal		Committed	2317648
Batch:	1587518 - Inspection Batch			Route:	SI_North_Q_08_MEIR HEATH		Date:	11/05/2023
1390831	Highway Carriageway Repairs - T2. Renew give way lines to be patched over.	11/05/2023	On give way l8nes at the junction with Lightwood Road.	CW - Pothole	Internal		Committed	2309460
Batch:	1579102 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	04/04/2023
1385493	Highway Carriageway Repairs - T3	04/04/2023	Opposite pool approx 311 metres from junction with the A5055 Lightwood Road travelling towards Cocknage from Rough Close.	CW - Cracking/Cracking	Internal		Committed	2239348
Batch:	1579100 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	04/04/2023
1385491	Highway Carriageway Repairs - Type 2	04/04/2023	Opposite access 5 mtrs before double bend sign	CW - Pothole	Internal		No Action Required	
Batch:	1565612 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	01/02/2023
1377802	Highway Carriageway Repairs - Type 3 please repair x4 carriageway potholes and associated cracking and fretting	01/02/2023	Just before entrance to Heather Lodge, 6 metres after Chevron Signs and x3 opposite Heather Lodge close to SLOW road markings	CW - Pothole	Internal		Committed	2257817
Batch:	1565601 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	01/02/2023
1377790	Highway Carriageway Repairs - T4	01/02/2023	Opposite pond by pull in parking area for Barlaston and Rough Close Common Local Nature Reserve.	CW - Pothole	Internal		No Action Required	
Batch:	1564865 - Inspection Batch			Route:	SI_North_Q_08_MEIR HEATH		Date:	27/01/2023
1377381	Highway Carriageway Repairs - T3. This job partsupersedes existing job number 2257817.	27/01/2023	Slightly on lowerside of access to Heather Lodge.	CW - Pothole	Internal		Committed	2300655

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Driven	Feature Type:	Inspected Network		Area:	S - Stone Rural North
Batch:	1560552 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	10/01/2023
1375137	Highway Carriageway Repairs - Type 3 please repair x4 carriageway potholes and associated cracking and fretting	10/01/2023	Just before entrance to Heather Lodge, CW - Pothole 6 metres after Chevron Signs and x3 opposite Heather Lodge close to SLOW road markings		Internal		No Action Required	
Batch:	1546874 - Inspection Batch No actionable defects found			Route:	SI_North_Q_08_MEIR HEATH		Date:	20/10/2022
Batch:	1529276 - Inspection Batch			Route:	SI_North_Q_08_MEIR HEATH		Date:	22/07/2022
1358610	Highway Carriageway Repairs - T4	22/07/2022	Opposite pond by pull in parking area for Barlaston and Rough Close Common Local Nature Reserve.	CW - Pothole	Internal		No Action Required	
Batch:	1512827 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	09/05/2022
1349774	Highway Carriageway Repairs - Type 3, CAT2, please repair x1 carriageway pothol This job supersedes in part, existing job number 2257818	09/05/2022	Outside property called Southbank	CW - Pothole	Internal		Committed	2278178
Batch:	1510067 - Inspection Batch No actionable defects found			Route:	SI_North_Q_08_MEIR HEATH		Date:	25/04/2022
Batch:	1491069 - Inspection Batch			Route:	SI_North_Q_08_MEIR HEATH		Date:	20/01/2022
1335419	Highway Carriageway Repairs - Type 3, CAT2, please repair x1 carriageway pothole This job supersedes in part existing job number 2257817	20/01/2022	Opposite property called Heather Lodge, 10 metres after Heather Lodge driveway, at end of kerb setts, on LHS of the carriageway heading towards Cocknage Wood	CW - Pothole	Internal		Committed	2266857
Batch:	1474761 - Inspection Batch			Route:	SI_North_Q_08_MEIR HEATH		Date:	22/10/2021
1325294	Highway Carriageway Repairs - Type 3 please repair x4 carriageway potholes and associated cracking and fretting	22/10/2021	Just before entrance to Heather Lodge, CW - Pothole 6 metres after Chevron Signs and x3 opposite Heather Lodge close to SLOW road markings		Internal		No Action Required	
1325293	Highway Carriageway Repairs - Type 3 please repair x5 carriageway potholes and associated cracking and fretting	22/10/2021	From outside property called Oakhurst up to property called Southbank on LHS of the carriageway heading towards the A5005	CW - Pothole	Internal		Committed	2257818
Batch:	1460213 - Inspection Batch No actionable defects found			Route:	SI_North_Q_08_MEIR HEATH		Date:	06/08/2021
Batch:	1441039 - Inspection Batch			Route:	SI_North_Q_08_MEIR HEATH		Date:	12/05/2021
1303661	Highway Signage Maintenance - clean graffiti off severe deviation chevron board.	11/05/2021	Approx 264 metres west of junction with TS - Graffiti/Dirty Lightwood Road opposite pond.		Internal		Committed	2239347
1303660	Highway Carriageway Repairs - T3	12/05/2021	Opposite pool approx 311 metres from junction with the A5055 Lightwood Road travelling towards Cocknage from Rough Close.	CW - Cracking/Cracking	Internal		No Action Required	

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Driven	Feature Type:	Inspected Network		Area:	S - Stone Rural North
Batch:	1418973 - Inspection Batch			Route:	SI_North_Q_08_MEIR HEATH		Date:	28/01/2021
1289767	Highway Signage Repairs - replace a displaced 76mm post standing approx 1.5 metres out of the ground. Replace 2 x securing bands and fasten severe deviation board to new post. Remove old post with lump of concrete on the base from site. Inspector has placed a cone at base of old post to warn/guard.	28/01/2021	On outside of bend opposite pool.	TS - Damaged/Missing	Internal		Committed	2228019
Batch:	1402931 - Inspection Batch			Route:	SI_North_Q_08_MEIR HEATH		Date:	05/11/2020
1280773	Highway Carriageway Repairs - Type 2	05/11/2020	5 mtrs before slow marked on road	CW - Pothole	Internal		No Action Required	
1280772	Highway Carriageway Repairs - Type 2	05/11/2020	Opposite access 5 mtrs before double bend sign	CW - Pothole	Internal		No Action Required	
Batch:	1384666 - Inspection Batch			Route:	SI_North_Q_08_MEIR HEATH		Date:	31/07/2020
1271005	Highway Carriageway Repairs - T3 x 1. This job supersedes existing job number 2193998. (Job 1 of 2).	31/07/2020	In VAC to property called Heather Lodge.	CW - Edge Failure	Internal		Committed	2212108
1271004	Highway Road Marking Repairs - refresh slow road marker.	31/07/2020	On lowerside of access to property called Heather Lodge.	RMark - Worn	Internal		Committed	2212110
1271003	Highway Carriageway Repairs - T3 x 1. This job supersedes existing job number 2193998. (Job 2 of 2).	31/07/2020	In VAC to property called Heather Lodge.	CW - Edge Failure	Internal		Committed	2212109
Batch:	1382465 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	21/07/2020
1269727	Highway Drainage Works -new carriageway gully requires emptying	21/07/2020	Outside the property called church house	Blocked Gully Wagon Required	Internal		Action Required	
Batch:	1376405 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	22/06/2020
1266134	Highway Carriageway Repairs - Type 3 x2	22/06/2020	Approximately 10m after the entrance to the property called heather lodge	CW - Pothole	Internal		Committed	2207815
Batch:	1376401 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	22/06/2020
1266131	Highway Carriageway Repairs - Type 3 x4 This job supersedes job no 2195690.	22/06/2020	Approximately 10m before the property called heather lodge	CW - Pothole	Internal		Committed	2207813
Batch:	1364890 - Inspection Batch			Route:	SI_North_Q_08_MEIR HEATH		Date:	22/04/2020
	No actionable defects found							
Batch:	1361494 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	06/04/2020
1257870	Type 3. X 2. Wet not marked.	06/04/2020	Travelling towards Cocknage located on left just after access to Heather Lodge before chevron boards.	CW - Pothole	Internal		Committed	2195690
Batch:	1358583 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	24/03/2020
1256041	Highway Carriageway Repairs - Type 3	24/03/2020	Just after the slow road markings by the property called heather lodge	CW - Pothole	Internal		Committed	2198857

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Driven	Feature Type:	Inspected Network		Area:	S - Stone Rural North
Batch:	1357402 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	19/03/2020
1255393	FOR INFORMATION ONLY- Highway Footway Cleansing Works - 18/03/20, time of completion 18:30hrs, Inspector cleared away over ridden mud/verge from footway and hand swept footway.	19/03/2020	Crossing point footway cocknage road side of lightwood road	FW/CY - Debris	Internal		Uncommitted	2198374
Batch:	1351560 - Inspection Batch			Route:	SI_North_Q_08_MEIR HEATH		Date:	13/02/2020
1251928	Type 3. X 2. Wet not marked.	13/02/2020	Travelling towards Cocknage located on left just after access to Heather Lodge before chevron boards.	CW - Pothole	Internal		No Action Required	
1251927	Type 3. X 1. Wet not marked.	13/02/2020	In centre of road just below access to Heather Lodge.	CW - Pothole	Internal		Committed	2195692
1251926	Type 3. X 1. This job supersedes existing job number 2137070.	13/02/2020	Travelling towards Rough Close and situated on left on inside of bend just past access to Heather Lodge.	CW - Pothole	Internal		Committed	2195691
Batch:	1348038 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	24/01/2020
1249751	Type 3 x1	24/01/2020	In the vehicular access to the property called Heather lodge	CW - Pothole	Internal		Committed	2193998
Batch:	1346699 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	17/01/2020
1248936	Cut and patch pothole. Wet not marked. (GPS not working).	17/01/2020	Just before access to Heather Lodge on lower side of access but on opposite side of carriageway.	CW - Pothole	Internal		Committed	2137070
Batch:	1334730 - Inspection Batch			Route:	SI_North_Q_08_MEIR HEATH		Date:	13/11/2019
1242891	Dig down in verge and replace broken 7inch salt glazed highway drainage pipe. Cone has been placed over by Inspector to warn/guard.	13/11/2019	Opposite gates to property called Church House approx 40 metres from jct with Lightwood Road.	DRAIN Other	Internal		Committed	2188507
1242890	FOR INFO ONLY - broken highway drain in verge, Inspector has plscd cone over to warn/guard until pipe can be replaced.	13/11/2019	In verge opposite gates to property called Church House approx 40 metres from jct with Lightwood Road.	DRAIN Other	Internal		Uncommitted	2188508
Batch:	1320121 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	27/08/2019
1236004	FOR INFO ONLY, TREE SURGEON ATTENDED AT 2AM ON 27TH AUGUST TO REMOVE FALLEN TREE, INCIDENT 34 (rob keysor)	27/08/2019	Near lightwood road	OOH Other	Internal		Committed	2182143
Batch:	1317990 - Inspection Batch			Route:	SI_North_Q_08_MEIR HEATH		Date:	15/08/2019
1235086	Cut back hedgerow from around give way warning sign so thst sign can be seen on approach to the junction. Pole shears required here.	15/08/2019	By Church House st junction with Lightwood Road.	TRHE Obscuring Street Furn	Internal		Committed	2181339
Batch:	1299854 - Inspection Batch			Route:	SI_North_Q_08_MEIR HEATH		Date:	16/05/2019
	No actionable defects found							

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Driven	Feature Type:	Inspected Network		Area:	S - Stone Rural North
Batch:	1282787 - Inspection Batch			Route:	SI_North_Q_08_MEIR HEATH		Date:	11/02/2019
	No actionable defects found							
Batch:	1269127 - Inspection Batch			Route:	SI_North_Q_08_MEIR HEATH		Date:	13/11/2018
	No actionable defects found							
Batch:	1253165 - Adhoc/Reactive Inspections			Route:	Adhoc/Reactive Inspections		Date:	20/05/2016
1203255	clear and jet all gullies from Church House also try and lightly jet pipe which goes under the drive of Lane End then continue down the road also check and clear any that are buried in edge of verges Report any problem which might require further work NOTE Roy Carr to be contact 48hrs before work commences	20/05/2016	starting o/s church house first on RHS of drive	DRAIN Gully Emptying	Internal		Committed	2084285
Batch:	1250740 - Inspection Batch			Route:	SI_North_Q_08_MEIR HEATH		Date:	14/08/2018
1200555	Cut back hedgerow obscuring give way sign. Pole shears required here.	14/08/2018	At junction with Lightwood Road.	TRHE Obscuring Street Furn	Internal		Committed	2153980
Batch:	1233206 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	23/05/2018
1192720	Cut and patch pothole. Wet not marked. (GPS not working).	23/05/2018	Just before access to Heather Lodge on lower side of access but on opposite side of carriageway.	CW - Pothole	Internal		No Action Required	
Batch:	1231383 - Inspection Batch			Route:	SI_North_Q_08_MEIR HEATH		Date:	15/05/2018
	No actionable defects found							
Batch:	1224203 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	10/04/2018
1187614	Fill the carriageway pothole, not marked due to the location. Approximately 0.5sqm	10/04/2018	outside heather lodge, by the chevrons	CW - Pothole	Internal		Committed	2142104
Batch:	1224202 - Inspection Batch			Route:	Adhoc/Reactive Inspections		Date:	10/04/2018
1187613	Fill the carriageway pothole, not marked due to the location. Approximately 1sqm	10/04/2018	Outside Heather cottage, opposite the slow road marking.	CW - Pothole	Internal		Committed	2142103
Batch:	1214397 - Inspection Batch			Route:	SI_North_Q_08_MEIR HEATH		Date:	15/02/2018
1181998	Replace 1 x missing post 80mm in diameter and 1 x missing severe deviation board sign face fig no. 515. Sign face measures 1.20m x 0.40m	15/02/2018	On outside of bend opposite pond. (NOTE GPS not working).	ULTS Missing/Broken	Internal		Committed	2137071
1181999	Cut and patch pothole. Wet not marked. (GPS not working).	15/02/2018	Just before access to Heather Lodge on lower side of access but on opposite side of carriageway.	CW - Pothole	Internal		No Action Required	
Batch:	1198372 - Inspection Batch			Route:	SI_North_Q_08_MEIR HEATH		Date:	10/11/2017
	No actionable defects found							
Batch:	1182026 - Inspection Batch			Route:	SI_North_Q_08_MEIR HEATH		Date:	11/08/2017
1165993	Replace cross roads sign ref 504-1 for SIZE 750MM	11/08/2017	50m rom Lightwood road	ULTS Dirty/Worn	Internal		Committed	2120784

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1.00	Asset - Locn.: Driven			Feature Type: Inspected Network			Area: S - Stone Rural North	
Batch: 1182026 - Inspection Batch				Route: SI_North_Q_08_MEIR HEATH			Date: 11/08/2017	
1165992	Mechanical road sweeper required to remove loose gravel	11/08/2017	Befor double chevron bend at Stoke boundry to bends sign	CW - Debris	Internal		Committed	2120785
Batch: 1165461 - Inspection Batch	No actionable defects found			Route: SI_North_Q_08_MEIR HEATH			Date: 11/05/2017	
Batch: 1152297 - Inspection Batch				Route: Adhoc/Reactive Inspections			Date: 07/03/2017	
1151762	Cut and patch pothole marked. Approximately 0.5sqm	07/03/2017	By the chevron signs just past Heather lodge.	CW - Pothole	Internal		Committed	2107511
Batch: 1149556 - Inspection Batch	No actionable defects found			Route: SI_North_Q_08_MEIR HEATH			Date: 15/02/2017	
Batch: 1136351 - Inspection Batch	No actionable defects found			Route: SI_North_Q_08_MEIR HEATH			Date: 15/11/2016	
Batch: 1120291 - Inspection Batch	No actionable defects found			Route: SI_North_Q_08_MEIR HEATH			Date: 11/08/2016	
Batch: 1104163 - Inspection Batch				Route: SI_North_Q_08_MEIR HEATH			Date: 12/05/2016	
1047632	Replace 75mm diametre post standing approx 4 foot out of the ground. Transfer existing severe deviation chevron board to new post and existing. Chevron board still on site.	12/05/2016	On bend opposite pool.	TS - Damaged/Missing	Internal		Committed	2083407
Batch: 1087647 - Inspection Batch	No actionable defects found			Route: SI_North_Q_08_MEIR HEATH			Date: 01/02/2016	
Batch: 1074417 - Inspection Batch	No actionable defects found			Route: SI_North_Q_08_MEIR HEATH			Date: 04/11/2015	
Batch: 1061525 - Inspection Batch	No actionable defects found			Route: SI_North_Q_08_MEIR HEATH			Date: 17/08/2015	
Batch: 1059032 - CW SI Qtly-01/08/2014- [REDACTED]	No actionable defects found			Route: Historic CW SI_Quarterly			Date: 01/08/2014	
Batch: 1059026 - CW SI Qtly-14/05/2014- [REDACTED]	No actionable defects found			Route: Historic CW SI_Quarterly			Date: 14/05/2014	
Batch: 1058854 - CW SI Qtly-29/01/2014- [REDACTED]	No actionable defects found			Route: Historic CW SI_Quarterly			Date: 29/01/2014	
Batch: 1057845 - CW SI Annual-01/10/2013- [REDACTED]	No actionable defects found			Route: Historic CW SI_Annual			Date: 01/10/2013	
Batch: 1057818 - CW SI Qtly-07/02/2013- [REDACTED]	No actionable defects found			Route: Historic CW SI_Quarterly			Date: 07/02/2013	
Batch: 1057785 - CW SI Qtly-01/11/2013- [REDACTED]	No actionable defects found			Route: Historic CW SI_Quarterly			Date: 01/11/2013	

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Driven		Feature Type: Inspected Network			Area: S - Stone Rural North	
Batch: 1057445 - CW SI Qtly-07/08/2013				Route: Historic CW SI_Quarterly			Date: 07/08/2013	
No actionable defects found								
Batch: 1056667 - CW SI Qtly-08/05/2013				Route: Historic CW SI_Quarterly			Date: 08/05/2013	
No actionable defects found								
Batch: 1056135 - CW SI Qtly-26/10/2012				Route: Historic CW SI_Quarterly			Date: 26/10/2012	
No actionable defects found								
Batch: 1056102 - CW SI Annual-20/09/2012				Route: Historic CW SI_Annual			Date: 20/09/2012	
No actionable defects found								
Batch: 1034587 - Inspection Batch				Route: SI_North_Q_08_MEIR HEATH			Date: 07/05/2015	
1016277 Patch required 0.5mtrx0.5mtrx45mm ***WET NOT MARKED***	07/05/2015	On bad bend outside heather lodge	CW - Pothole	Internal		Archived		2033798
1016276 Patch required on carraigeway edge pothole 1mtr2 80mm ***WET NOT MARKED*** ***TOO DANGEROUS FOR PHOTOS***	07/05/2015	On bad bend opposite heather lodge above slow road marker	CW - Pothole	Internal		Archived		2033799
Batch: 1024021 - Inspection Batch				Route: SI_North_Q_08_MEIR HEATH			Date: 04/03/2015	
No actionable defects found								
Batch: 1010110 - Inspection Batch				Route: SI_North_Q_08_MEIR HEATH			Date: 04/12/2014	
No actionable defects found								
Asset:	10,001.00	Asset - Locn.: 151880		Feature Type: Drainage Asset - Gully			Area: zzS - Stone Rural	
Batch: 30277544 - Inspection Batch				Route: Gully 2 - Biennial Pack 004			Date: 18/05/2021	
No actionable defects found								
Batch: 30101205 - Inspection Batch				Route: Gully 2 - Biennial Pack 004			Date: 25/06/2019	
30036067	25/06/2019		CW - Gully Lid Jammed	Internal		No Action Required		
30036066	25/06/2019		Blocked Jetting Required	Internal		No Action Required		
Batch: 30018388 - 02/11/2015 Historic Inspection				Route: Gully Historic Import			Date: 02/11/2015	
No actionable defects found								
Asset:	10,002.00	Asset - Locn.: 151881		Feature Type: Drainage Asset - Gully			Area: S - Stone Rural North	
Batch: 30594411 - Inspection Batch				Route: Gully 2 - Biennial Pack 004			Date: 08/08/2025	
No actionable defects found								
Batch: 30277512 - Inspection Batch				Route: Gully 2 - Biennial Pack 004			Date: 18/05/2021	
No actionable defects found								
Batch: 30101250 - Inspection Batch				Route: Gully 2 - Biennial Pack 004			Date: 25/06/2019	
No actionable defects found								
Batch: 30018388 - 02/11/2015 Historic Inspection				Route: Gully Historic Import			Date: 02/11/2015	
No actionable defects found								

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 10,003.00	Asset - Locn.: 151882			Feature Type: Drainage Asset - Gully			Area: S - Stone Rural North	
Batch: 30594413 - Inspection Batch	No actionable defects found			Route: Gully 2 - Biennial Pack 004			Date: 08/08/2025	
Batch: 30277515 - Inspection Batch	No actionable defects found			Route: Gully 2 - Biennial Pack 004			Date: 18/05/2021	
Batch: 30101248 - Inspection Batch	No actionable defects found			Route: Gully 2 - Biennial Pack 004			Date: 25/06/2019	
Batch: 30018388 - 02/11/2015 Historic Inspection	No actionable defects found			Route: Gully Historic Import			Date: 02/11/2015	
Asset: 10,004.00	Asset - Locn.: 151883			Feature Type: Drainage Asset - Gully			Area: S - Stone Rural North	
Batch: 30594424 - Inspection Batch	No actionable defects found			Route: Gully 2 - Biennial Pack 004			Date: 08/08/2025	
Batch: 30277520 - Inspection Batch				Route: Gully 2 - Biennial Pack 004			Date: 18/05/2021	
30048264		18/05/2021		CW - Gully Lid Jammed	Internal		Committed	30010362
Batch: 30101247 - Inspection Batch	No actionable defects found			Route: Gully 2 - Biennial Pack 004			Date: 25/06/2019	
Batch: 30018388 - 02/11/2015 Historic Inspection	No actionable defects found			Route: Gully Historic Import			Date: 02/11/2015	
Asset: 10,005.00	Asset - Locn.: 151884			Feature Type: Drainage Asset - Gully			Area: S - Stone Rural North	
Batch: 30594442 - Inspection Batch	No actionable defects found			Route: Gully 2 - Biennial Pack 004			Date: 08/08/2025	
Batch: 30277546 - Inspection Batch	No actionable defects found			Route: Gully 2 - Biennial Pack 004			Date: 18/05/2021	
Batch: 30101246 - Inspection Batch	No actionable defects found			Route: Gully 2 - Biennial Pack 004			Date: 25/06/2019	
Batch: 30018388 - 02/11/2015 Historic Inspection	No actionable defects found			Route: Gully Historic Import			Date: 02/11/2015	
Batch: 1802996 - Inspection Batch				Route: Adhoc/Reactive Inspections			Date: 30/10/2025	
1511468	Pre-Surface Dressing 2026works site 6537 reset ully	30/10/2025	Just down from lay-by	CW - Ironwork Loose/Rocking	Internal		Committed	2406102
Batch: 1564863 - Inspection Batch				Route: Adhoc/Reactive Inspections			Date: 27/01/2023	
1377380	Highway Ironwork Repairs - reset loose gully where marked.	27/01/2023	Opposite pool approx 311 metres from junction with the A5055 Lightwood Road travelling towards Cocknage from Rough Close.	CW - Ironwork Loose/Rocking	Internal		Committed	2300654
Asset: 10,006.00	Asset - Locn.: 151885			Feature Type: Drainage Asset - Gully			Area: S - Stone Rural North	
Batch: 30594457 - Inspection Batch	No actionable defects found			Route: Gully 2 - Biennial Pack 004			Date: 08/08/2025	

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 10,006.00 Asset - Locn.: 151885				Feature Type: Drainage Asset - Gully		Area: S - Stone Rural North		
Batch: 30277547 - Inspection Batch				Route: Gully 2 - Biennial Pack 004		Date: 18/05/2021		
30048269		18/05/2021		CW - Gully Lid Jammed	Internal		Committed	30010365
Batch: 30101245 - Inspection Batch No actionable defects found				Route: Gully 2 - Biennial Pack 004		Date: 25/06/2019		
Batch: 30018388 - 02/11/2015 Historic Inspection No actionable defects found				Route: Gully Historic Import		Date: 02/11/2015		
Batch: 1868673 - Inspection Batch				Route: Adhoc/Reactive Inspections		Date: 23/07/2026		
1551033	Highway Drainage Works - empty and jet blocked gully.	23/07/2026	Travelling towards Cocknage and located on the left just before the culverted water course.	Blocked Gully Wagon Required	Internal		Committed	2328074
Batch: 1717955 - Inspection Batch				Route: Adhoc/Reactive Inspections		Date: 25/10/2024		
1465570	Highway Drainage Works - empty and jet blocked gully.	25/10/2024	Travelling towards Cocknage and located on the left just before the culverted water course.	Blocked Gully Wagon Required	Internal		No Action Required	
Batch: 1637614 - Inspection Batch				Route: Adhoc/Reactive Inspections		Date: 18/12/2023		
1415916	Highway Drainage Works - empty and jet blocked gully.	18/12/2023	Travelling towards Cocknage and located on the left just before the culverted water course.	Blocked Gully Wagon Required	Internal		No Action Required	
Batch: 1637613 - Inspection Batch				Route: Adhoc/Reactive Inspections		Date: 18/12/2023		
1415915	Highway Ironwork Repairs - replace defective gully with jammed lid.	18/12/2023	Travelling towards Cocknage and located on the left just before the culverted water course.	CW - Ironwork Defective	Internal		Committed	2328073
Asset: 10,007.00 Asset - Locn.: 151923				Feature Type: Drainage Asset - Gully		Area: S - Stone Rural North		
Batch: 30594392 - Inspection Batch No actionable defects found				Route: Gully 2 - Biennial Pack 004		Date: 08/08/2025		
Batch: 30277529 - Inspection Batch				Route: Drainage - Adhoc		Date: 18/05/2021		
30048265		18/05/2021		CW - Gully Lid Jammed	Internal		Action Required	
Batch: 30277527 - Inspection Batch No actionable defects found				Route: Gully 2 - Biennial Pack 004		Date: 18/05/2021		
Batch: 30101210 - Inspection Batch				Route: Gully 2 - Biennial Pack 004		Date: 25/06/2019		
30036069		25/06/2019		CW - Gully Lid Jammed	Internal		No Action Required	
30036068		25/06/2019		Blocked Carrier (Non SCC)	Internal		Action Required	
Batch: 30017693 - 2015 Historic Inspection				Route: Gully Historic Import		Date: 02/11/2015		
30024306		02/11/2015		Blocked Carrier (Non SCC)	Internal		No Action Required	
Asset: 10,008.00 Asset - Locn.: 151926				Feature Type: Drainage Asset - Gully		Area: S - Stone Rural North		
Batch: 30594398 - Inspection Batch No actionable defects found				Route: Gully 2 - Biennial Pack 004		Date: 08/08/2025		
Batch: 30277543 - Inspection Batch				Route: Gully 2 - Biennial Pack 004		Date: 18/05/2021		
30048268		18/05/2021		Blocked Jetting Required	Internal		Committed	30010364

Effective: 10/09/2012 to 10/09/2026

Service: Highway Operations

Display Action Officer: No

Site: COCKNAGE ROAD (37601017)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	10,008.00	Asset - Locn.:	151926	Feature Type:	Drainage Asset - Gully	Area:	S - Stone Rural North	
Batch:	30277543 - Inspection Batch			Route:	Gully 2 - Biennial Pack 004			Date: 18/05/2021
30048267		18/05/2021	Outside the property called Braemar.	Blocked Gully Wagon Required	Internal		Archived	30010363
Batch:	30101249 - Inspection Batch			Route:	Gully 2 - Biennial Pack 004			Date: 25/06/2019
	No actionable defects found							
Batch:	30018388 - 02/11/2015 Historic Inspection			Route:	Gully Historic Import			Date: 02/11/2015
	No actionable defects found							
Batch:	1317358 - Inspection Batch			Route:	Adhoc/Reactive Inspections			Date: 13/08/2019
1234831		13/08/2019	Outside the property called Braemar.	Blocked Gully Wagon Required	Internal		No Action Required	
Asset:	10,009.00	Asset - Locn.:	151927	Feature Type:	Drainage Asset - Gully	Area:	S - Stone Rural North	
Batch:	30594404 - Inspection Batch			Route:	Gully 2 - Biennial Pack 004			Date: 08/08/2025
	No actionable defects found							
Batch:	30277545 - Inspection Batch			Route:	Gully 2 - Biennial Pack 004			Date: 18/05/2021
	No actionable defects found							
Batch:	30101206 - Inspection Batch			Route:	Gully 2 - Biennial Pack 004			Date: 25/06/2019
	No actionable defects found							
Batch:	30018388 - 02/11/2015 Historic Inspection			Route:	Gully Historic Import			Date: 02/11/2015
	No actionable defects found							
Asset:	99,999,999.00	Asset - Locn.:		Feature Type:	Whole Site Feature	Area:	S - Stone Rural North	
Batch:	1030682 - Inspection Batch			Route:	Adhoc/Reactive Inspections			Date: 16/04/2015
	No actionable defects found							

Customer Services

Enquiry No.:	4511829	Logged by:	CRM JADU	on:	28/08/2026 14:56
Service:	Highway Operations	Subject:	Drain Blocked Gully	Classification:	General Enquiry
Desc.:	This problem is on a recently repaired and resurfaced piece of road. The flooding issue was reported before the repair took place, maybe sometime in the preceding 18 months ago, when the road surface disintegrated due to standing water. Unfortunately the drain and drainage issue have not been rectified before the new surface laid. This is a recent issue here, only happening in the last two years, and if it is not addressed there will be serious issues due to flooding especially in the winter months when it will be prone to freezing.				
Location:	Flooding not far from the pond on Cocknage Road just down from Rough Close school.		Contact:		
Plot Number:	1.00	Feature Id - Location:	Driven	Feature Type:	Inspected Network

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Customer Services

Enquiry No.: 4496444 Logged by: CRM JADU on: 01/05/2026 08:58

Service: Highway Operations Subject: Carriageway Pothole Multiple Classification: General Enquiry

Desc.: Good morning.

The pothole was repaired yesterday at the junction of Cocknage Road and Lightwood Road in Rough Close

While this is welcome, the poor repair in the area which is most prone to re-occur, the finished surface on the remaining repair is of a good standard. I believe that it won't be long before this starts to degrade again because it wasn't finished properly, almost like they ran out of tarmac.

Location: The junction of Cocknage Road and Lightwood Road in Rough Close What 3 words Contact:
location

///awesome.handed.irritate

Plot Number: 1.00 Feature Id - Location: Driven Feature Type: Inspected Network

Enquiry No.: 4492784 Logged by: CRM JADU on: 08/04/2026 14:52

Service: Highway Operations Subject: CW Pothole Classification: General Enquiry

Desc.: There is a cluster of 3 (I think) rather big and deep looking potholes.

Location: Nothing notifiable around the area. Contact:

Plot Number: 1.00 Feature Id - Location: Driven Feature Type: Inspected Network

Enquiry No.: 4462221 Logged by: CRM JADU on: 21/11/2025 17:50

Service: Highway Operations Subject: CW Pothole Classification: General Enquiry

Desc.: There is a huge pot hole that is damaging cars, apparently it's been there for quite some time as last year there was a wreck from it.

At the moment it is filling with water/ice and is just beyond the bend so people struggle to see it.

Location: If you go past the pond on cocknage road so that it is on the right hand side the pot Contact:
hole is about 150 yards past it on the left. It's between the pond and a non named
track that goes to the left. There are multiple pot holes, but one has damaged 2
wheels today.

Plot Number: 1.00 Feature Id - Location: Driven Feature Type: Inspected Network

Job Number: 2408432 Defect Number: 1551032

Enquiry No.: 4453470 Logged by: CRM JADU on: 09/09/2025 21:00

Service: Highway Operations Subject: CW Pothole Classification: General Enquiry

Desc.: Pothole

Location: Arond the bend on the left hand side Contact:

Plot Number: 1.00 Feature Id - Location: Driven Feature Type: Inspected Network

Job Number: 2403910 Defect Number: 1509053

Enquiry No.: 4448735 Logged by: CRM JADU on: 28/07/2025 10:15

Service: Highway Operations Subject: Unlit TS Damage/Missing/Worn Classification: Classified - Emergency

Desc.: Three arrows, black white sign advising of bend approaching is missing, it is on the verge. Verge dangerous as people may not be warned about the corner.

Location: Along the Cocknage road just after the Pond and the corner. Contact:

Plot Number: 1.00 Feature Id - Location: Driven Feature Type: Inspected Network

Effective: 10/09/2012 to 10/09/2026

Service: Highway Operations

Display Action Officer: No

Site: COCKNAGE ROAD (37601017)

Customer Services

Enquiry No.: 4435929	Logged by: CRM JADU	on: 31/03/2025 12:33
Service: Highway Operations	Subject: Carriageway Pothole Multiple	Classification: General Enquiry
Desc.: There are several potholes at this location; to avoid them, it is necessary to move over to the opposite side of the road, causing a dangerous situation on this very sharp bend.		
Location: Cocknage Road, Riugh Close, Grid ref, SJ91939866, whatthreewords, perch.professes.flagged		Contact:
Plot Number: 1.00	Feature Id - Location: Driven	Feature Type: Inspected Network
Job Number: 2387381	Defect Number: 1489955	
Enquiry No.: 4434522	Logged by: CRM JADU	on: 21/03/2025 07:24
Service: Highway Operations	Subject: Carriageway Pothole Multiple	Classification: General Enquiry
Desc.: Cars avoiding the pothole on the wrong side of the carriageway on a corner. Several potholes on this section.		
Location: On your boundary on a corner. What 3 words ///wealth.magnum.flickers.		Contact:
Plot Number: 1.00	Feature Id - Location: Driven	Feature Type: Inspected Network
Job Number: 2387381	Defect Number: 1489955	
Enquiry No.: 4432217	Logged by: CRM JADU	on: 05/03/2025 18:33
Service: Highway Operations	Subject: Unlit TS Damage/Missing/Worn	Classification: General Enquiry
Desc.: chevrons sign damaged		
Location: Cocknage Road, Rough Close, first sharp bend by pond		Contact:
Plot Number: 1.00	Feature Id - Location: Driven	Feature Type: Inspected Network
Job Number: 2367364	Defect Number: 1489939	
Enquiry No.: 4424463	Logged by: CRM JADU	on: 21/01/2025 20:32
Service: Highway Operations	Subject: CW Pothole	Classification: Classified - Emergency
Desc.: Large pot hole on bend by pond cocknage road		
Location: Large pot hole on bend by pond cocknage road		Contact:
Plot Number: 1.00	Feature Id - Location: Driven	Feature Type: Inspected Network
Job Number: 2387378	Defect Number: 1551021	
Enquiry No.: 4414736	Logged by: CRM Connector	on: 20/11/2024 14:59
Service: Highway Operations	Subject: ARBS - Tree Fallen/Overgrown	Classification: Classified - Emergency
Desc.: Weeds, trees, verges and hedges-Fallen tree or branch [not on road]		
Date noticed 20 November 2024, Fallen Branch/tree on Cocknage road near to the small pond,		
Location: On Cocknage road		Contact: [REDACTED]
Enquiry No.: 4414636	Logged by: CRM Connector	on: 19/11/2024 19:37
Service: Highway Operations	Subject: ARBS - Tree Fallen/Overgrown	Classification: General Enquiry
Desc.: Weeds, trees, verges and hedges-Fallen tree or branch [not on road]		
Date noticed 19 November 2024, Damaged tree/branches hanging over carriageway so only way past is driving partially on opposite grass verge one car at a time,		
Location: Near the pond on the pond side of the road		Contact: [REDACTED]

Effective: 10/09/2012 to 10/09/2026

Service: Highway Operations

Display Action Officer: No

Site: COCKNAGE ROAD (37601017)

Customer Services

Enquiry No.: 4408720			Logged by: CRM Connector	on: 01/10/2024 18:41
Service: Highway Operations			Subject: Drain Blocked Gully	Classification: General Enquiry
Desc.: Drains and manholes-Blocked drain				
Date noticed 01 October 2024, Your teams have just completed a number of repairs in this area. Ref 4362567. Whilst the repair to the surface was welcome, the blocked drain that repeatedly causes the flooding, which damaged the road surface in the first place - is still blocked. The road is still flooded. The repair will soon be damaged again.,				
Location: Same location as job 4362567			Contact: [REDACTED]	
Plot Number: 10,006.00	Feature Id - Location: 151885			Feature Type: Drainage Asset - Gully
Job Number: 2328074	Defect Number: 1551033			
Enquiry No.: 4400117			Logged by: CRM Connector	on: 27/07/2024 17:14
Service: Highway Operations			Subject: CW Pothole	Classification: General Enquiry
Desc.: Road damage-Edge failure				
Date noticed 26 July 2024, Pothole near the kerb on the line of nearside wheels. Abrupt front wall about 10 cm deep with long damage preceding it in the direction of travel.,				
Approximate size (width, depth etc.)* - Approximately 1 metre long by approximately 45 cm wide by over 10 cm deep at the deepest point.				
Location: Driving lane. ST3 7NN On Cocknage Road, Rough Close, about 300 metres WSW of the junction with Lightwood Road. Opposite the pool and close to the layby and entrance to Barlaston and Rough Close Country Park, on the same side.			Contact: [REDACTED]	
Enquiry No.: 4377338			Logged by: CRM Connector	on: 13/03/2024 12:58
Service: Highway Operations			Subject: CW Pothole	Classification: General Enquiry
Desc.: Road damage-Defect near ironwork				
Date noticed 13 March 2024, Failure to properly fix and fill a previously reported massive hole in the road as indicated by the map. This has now been filled twice to almost no avail. The actual road level has subsided somewhat since the original reporting with further sever crazing and flooding. Th3 flooding is being caused by the incorrect road level, poor filing of potholes and an extremely blocked drain. This drain may even have cracked also due to poor maintenance. This whole stretch of Cocknage Road needs attention as it now results in serious flooding after rainfall.,				
Approximate size (width, depth etc.)* - BIG				
Location: Driving lane. See map			Contact: [REDACTED]	
Plot Number: 1.00	Feature Id - Location: Driven			Feature Type: Inspected Network
Job Number: 2329906	Defect Number: 1444985			
Enquiry No.: 4366254			Logged by: CRM Connector	on: 01/02/2024 10:50
Service: Highway Operations			Subject: CW Pothole	Classification: General Enquiry
Desc.: Road damage-Edge failure				
Date noticed 12 December 2023, Hole in the road,				
Approximate size (width, depth etc.)* - 24? x 24?				
Location: Kerb. St3 7nn			Contact: [REDACTED]	
Plot Number: 1.00	Feature Id - Location: Driven			Feature Type: Inspected Network
Job Number: 2329906	Defect Number: 1444985			

Effective: 10/09/2012 to 10/09/2026

Service: Highway Operations

Display Action Officer: No

Site: COCKNAGE ROAD (37601017)

Customer Services

Enquiry No.: 4365975	Logged by: CRM Connector	on: 31/01/2024 06:33
Service: Highway Operations	Subject: CW Pothole	Classification: General Enquiry
Desc.: Road damage-Edge failure		
Date noticed 02 January 2024, Deep pothole,		
Approximate size (width, depth etc.)* - Unable to provide further info		
Location: Kerb. It is on a bend and does need to be avoided which in turn is also dangerous.	Contact:	
Plot Number: 1.00	Feature Id - Location: Driven	Feature Type: Inspected Network
Job Number: 2285634	Defect Number: 1444979	
Enquiry No.: 4360253	Logged by: CRM Connector	on: 04/01/2024 14:42
Service: Highway Operations	Subject: CW Pothole	Classification: General Enquiry
Desc.: Road damage-Edge failure		
Date noticed 04 January 2024, Erosion of the side of the road surface. Quite deep, would damage vehicles and is very dangerous to cyclists,		
Approximate size (width, depth etc.)* - 3 feet long x 1 foot x 4inches deep		
Location: Driving lane. Just last the bad left hand bend going towards Rough Close from Barlaston rd. hole situated on Cocknage Road	Contact:	
Plot Number: 1.00	Feature Id - Location: Driven	Feature Type: Inspected Network
Job Number: 2220368	Defect Number: 1444994	
Enquiry No.: 4359583	Logged by: CRM Connector	on: 02/01/2024 20:35
Service: Highway Operations	Subject: CW Pothole	Classification: General Enquiry
Desc.: Road damage-Pothole		
Date noticed 12 December 2023, A huge hole in the road which was deep and full of rainwater. To avoid this hole you would have to drive on the opposite side of the road towards oncoming vehicles. With no moonlight and torrential rain plus vehicle headlights coming towards you the hole was not visible.,		
Approximate size (width, depth etc.)* - Approx. 4ft wide, 6ft long, 6in deep		
Location: Driving lane. Cocknage Road, Rough Close, Stoke-on-Trent, ST3 next to Mill Stream	Contact:	
Plot Number: 1.00	Feature Id - Location: Driven	Feature Type: Inspected Network
Job Number: 2329904	Defect Number: 1418642	
Enquiry No.: 4358078	Logged by: CRM Connector	on: 26/12/2023 16:44
Service: Highway Operations	Subject: CW Pothole	Classification: General Enquiry
Desc.: Road damage-Pothole		
Date noticed 26 December 2023, Pothole in driving lane on corner.,		
Approximate size (width, depth etc.)* - 40cm wide		
Location: Driving lane. On corner on the stafford side of boundary.	Contact:	

Effective: 10/09/2012 to 10/09/2026

Service: Highway Operations

Display Action Officer: No

Site: COCKNAGE ROAD (37601017)

Customer Services

Enquiry No.: 4356405	Logged by: CRM Connector	on: 15/12/2023 14:26
Service: Highway Operations	Subject: CW Pothole	Classification: General Enquiry
Desc.: Road damage-Edge failure		
Date noticed 15 December 2023, flooded huge pothole that covers one side of the road.,		
Approximate size (width, depth etc.)* - 120cm approx		
Location: Driving lane. see ref 4309153 Cocknage Road	Contact: [REDACTED]	
Plot Number: 1.00	Feature Id - Location: Driven	Feature Type: Inspected Network
Job Number: 2328086	Defect Number: 1416382	
Enquiry No.: 4356237	Logged by: CRM Connector	on: 14/12/2023 22:05
Service: Highway Operations	Subject: CW Pothole	Classification: General Enquiry
Desc.: Road damage-Pothole		
Date noticed 13 December 2023, Severe damage to road surface resulting in large pothole. The damage reaches across two thirds of the road and the depth is approx 15cms. In wet weather the pot hole is obscured by standing water (drain ineffective),		
Approximate size (width, depth etc.)* - approx 1m length x 1.25m width x 15cm depth		
Location: Driving lane. The pothole is on the Cocknage Road, the nearest property is likely Rose Cottage. It is just past the lake (on opposite side of the road).	Contact: [REDACTED]	
Plot Number: 1.00	Feature Id - Location: Driven	Feature Type: Inspected Network
Job Number: 2328086	Defect Number: 1416382	
Enquiry No.: 4356168	Logged by: CRM Connector	on: 14/12/2023 16:16
Service: Highway Operations	Subject: CW Pothole	Classification: General Enquiry
Desc.: This relates to call Ref:4355075. damage to multiple cars including mine. Pothole appears to have gotten worse at 17.20 hours on Wednesday 13th December.,		
Location: Driving lane. Between pond and next bend	Contact: [REDACTED]	
Plot Number: 1.00	Feature Id - Location: Driven	Feature Type: Inspected Network
Job Number: 2328086	Defect Number: 1416382	
Enquiry No.: 4356071	Logged by: CRM Connector	on: 14/12/2023 11:21
Service: Highway Operations	Subject: CW Pothole	Classification: General Enquiry
Desc.: Road damage-Pothole		
Date noticed 13 December 2023, Absolutely huge crater on the left hand side of the road. Completely destroyed the wheel and tyre of my car,		
Approximate size (width, depth etc.)* - 1.5 metres squared wide. Unknown depth (at least 30cm)		
Location: Centre of road. Heading down Cocknage road from Common Lane. As you take the first bend (fishing pond on the right hand side) the pot hole is on the left hand side of the road.	Contact: [REDACTED]	
Plot Number: 1.00	Feature Id - Location: Driven	Feature Type: Inspected Network
Job Number: 2328086	Defect Number: 1416382	

Effective: 10/09/2012 to 10/09/2026

Service: Highway Operations

Display Action Officer: No

Site: COCKNAGE ROAD (37601017)

Customer Services

Enquiry No.: 4355939

Service: Highway Operations

Desc.: Road damage-Edge failure

Logged by: CRM Connector

Subject: CW Pothole

on: 13/12/2023 16:57

Classification: General Enquiry

Date noticed 11 December 2023, Road completely broken away for a large area (1.3m2) due to blocked metal drainage grid not draining. The damage reaches across two thirds of the carriageway and the depth is in excess of 14cms. When it rains the whole of this carriageway fills with water completely obscuring the pothole. This means that people will inevitably drive into the pothole thus further enlarging the hole. Photos are available.,

Approximate size (width, depth etc.)* - 1000mm length x 1200mm width x 140mm depth

Location: Driving lane. In Cocknage Road on the same side as the turning to Rose Cottage, just past the Lake (which is on the opposite side of the road). Travelling from Lightwood Road turn into Cocknage Road, the pot hole is on the left hand side just past the Lake (which is on the right hand side) The lane to Rose Cottage is off to the left just past the pothole. If one carried on past this turning the next road on the left would be Barlaston Road.

Contact: [REDACTED]

Plot Number: 1.00

Feature Id - Location: Driven

Feature Type: Inspected Network

Job Number: 2329904

Defect Number: 1418642

Enquiry No.: 4355877

Service: Highway Operations

Desc.: Road damage-Pothole

Logged by: CRM Connector

Subject: CW Pothole

on: 13/12/2023 13:37

Classification: General Enquiry

Date noticed 13 December 2023, Dangerous condition of road,

Approximate size (width, depth etc.)* - Very large & deep hole in road

Location: Kerb. In the kerb side of if road just by sign to Rose Cottage.

Contact: [REDACTED]

Plot Number: 1.00

Feature Id - Location: Driven

Feature Type: Inspected Network

Job Number: 2328086

Defect Number: 1416382

Enquiry No.: 4355793

Service: Highway Operations

Desc.: Road damage-Defect near ironwork

Logged by: CRM Connector

Subject: CW Pothole

on: 13/12/2023 10:04

Classification: General Enquiry

Date noticed 12 December 2023, A raised drain cover and a piece of concrete. Suspect the cover was lifted and the concrete exposed during heavy rainfall,

Approximate size (width, depth etc.)* - 40cm x40cm

Location: Driving lane. Approximately 300 yards from the Lightwood end of Cockanage road on the left hand side as you travel down the hill.

Contact: [REDACTED]

Plot Number: 1.00

Feature Id - Location: Driven

Feature Type: Inspected Network

Job Number: 2328086

Defect Number: 1416382

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Customer Services

Enquiry No.: 4355676 **Logged by:** CRM Connector **on:** 12/12/2023 20:10
Service: Highway Operations **Subject:** CW Pothole **Classification:** General Enquiry
Desc.: Road damage-Pothole

Date noticed 12 December 2023, Dangerous large pothole, growing daily, cars are hitting it and breaking down, having punctures. It?s on a slight bend and the hole is breaking up and growing.,

Approximate size (width, depth etc.)* - At least a metre square by 100mm deep

Location: Driving lane. ST3 4AA on Cocknage road near the entrance to Rose Cottage

Contact: [REDACTED]

Plot Number: 1.00 **Feature Id - Location:** Driven **Feature Type:** Inspected Network
Job Number: 2328086 **Defect Number:** 1416382

Enquiry No.: 4355075 **Logged by:** CRM Connector **on:** 11/12/2023 07:03
Service: Highway Operations **Subject:** CW Pothole **Classification:** General Enquiry
Desc.: Road damage-Pothole

Date noticed 11 December 2023, Large pothole,

Approximate size (width, depth etc.)* - 1000mm x500mm x 150mm

Location: Driving lane. Between pond and next bend

Contact: [REDACTED]

Plot Number: 1.00 **Feature Id - Location:** Driven **Feature Type:** Inspected Network
Job Number: 2328086 **Defect Number:** 1416382

Enquiry No.: 4319127 **Logged by:** CRM Connector **on:** 01/04/2023 12:58
Service: Highway Operations **Subject:** CW Pothole **Classification:** General Enquiry
Desc.: Road damage-Edge failure

Date noticed 01 April 2023, Large hole at edge of road,

Approximate size (width, depth etc.)* - 1.75 meters long, .5 wide and 8cm deep

Location: Driving lane. Cocknage Road towards Longton, past pond on roadside by bungalow

Contact: [REDACTED]

Plot Number: 1.00 **Feature Id - Location:** Driven **Feature Type:** Inspected Network
Job Number: 2220368 **Defect Number:** 1444994

Enquiry No.: 4319122 **Logged by:** CRM Connector **on:** 01/04/2023 12:51
Service: Highway Operations **Subject:** CW Pothole **Classification:** General Enquiry
Desc.: Road damage-Cracking

Date noticed 01 April 2023, Breaking up of road surface and several holes in this stretch especially round drain cover.,

Approximate size (width, depth etc.)* - 20 metres long, 1.5 meters wide, varying depths

Location: Driving lane. Just up Cocknage road from the pond going towards Rose Cottage.

Contact: [REDACTED]

Damage on left hand carriageway.

Plot Number: 1.00 **Feature Id - Location:** Driven **Feature Type:** Inspected Network
Job Number: 2239348 **Defect Number:** 1385493

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Customer Services

Enquiry No.: 4309771 Logged by: CRM Connector on: 03/02/2023 13:27
 Service: Highway Operations Subject: CW Pothole Classification: General Enquiry
 Desc.: Road damage-Edge failure

Date noticed 30 January 2023, Deep whole in road enough for a car tyre to go down,

Approximate size (width, depth etc.)* - Don't know exact measurements but deep enough and big enough for a car tyre to go down

Location: Driving lane. Situated by a large tree and a faded white slow sign

Contact: [REDACTED]

Enquiry No.: 4309154 Logged by: CRM Connector on: 31/01/2023 08:24
 Service: Highway Operations Subject: CW Pothole Classification: General Enquiry
 Desc.: Road damage-Pothole

Date noticed 16 January 2023, Pothole,

Approximate size (width, depth etc.)* - Unknown

Location: Driving lane. Kerbside, on a bend.

Contact: [REDACTED]

Plot Number: 1.00 Feature Id - Location: Driven Feature Type: Inspected Network
 Job Number: 2257817 Defect Number: 1377802

Enquiry No.: 4309153 Logged by: CRM Connector on: 31/01/2023 08:22
 Service: Highway Operations Subject: CW Pothole Classification: General Enquiry
 Desc.: Road damage-Pothole

Date noticed 16 January 2023, Pot hole,

Approximate size (width, depth etc.)* - Can't guess

Location: Kerb. On the bend, kerbside

Contact: [REDACTED]

Plot Number: 1.00 Feature Id - Location: Driven Feature Type: Inspected Network
 Job Number: 2285634 Defect Number: 1444979

Enquiry No.: 4304830 Logged by: CRM Connector on: 07/01/2023 15:20
 Service: Highway Operations Subject: CW Pothole Classification: General Enquiry
 Desc.: Road damage-Big pothole

Date noticed 07 January 2023, Erosion on the edge of the road, no curb.,

Approximate size (width, depth etc.)* - 5ft long x 1ft wide

Location: Kerb. Right hand side of road, just after the corner on Cocknage Road, heading towards Rough Close. Bungalow close by.

Contact: [REDACTED]

Plot Number: 1.00 Feature Id - Location: Driven Feature Type: Inspected Network
 Job Number: 2257817 Defect Number: 1377802

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Customer Services**Enquiry No.:** 4273499**Logged by:** CRM Connector**on:** 06/03/2022 19:46**Service:** Highway Operations**Subject:** CW Pothole**Classification:** General Enquiry**Desc.:** Road damage-Edge failure

Date noticed 06 March 2022, Deep holes throughout this area,

Approximate size (width, depth etc.)* - A number of dangerous potholes throughout this road that I would not like to hit on my motorcycle at any point

Location: Driving lane. Not sure, investigate and you will see!**Contact:** [REDACTED]**Enquiry No.:** 4253845**Logged by:** CRM Connector**on:** 30/08/2021 20:05**Service:** Highway Operations**Subject:** CW Pothole**Classification:** General Enquiry**Desc.:** Road damage-Pothole

Date noticed 26 August 2021, Huge pothole which we missed the other day but my sister hit it and it popped her tyre,

Approximate size (width, depth etc.)* - 12 inch?s

Location: Centre of road. Just up from the pond along cocknage road**Contact:** [REDACTED]**Enquiry No.:** 4248284**Logged by:** CRM Connector**on:** 07/07/2021 12:48**Service:** Highway Operations**Subject:** CW Pothole**Classification:** General Enquiry**Desc.:** Road damage-Edge failure

Date noticed 01 June 2021, Quite a large pot hole that appears to be getting worse.

Put date first noticed as 1/6/21 however I am confident it was much longer ago.,

Approximate size (width, depth etc.)* - Don't know

Location: Kerb. as driving from Rough Close towards Barlaston Road, it is located on the left very close to the right hand bend.**Contact:** [REDACTED]

PLEASE NOT THAT THERE IS AN ADDITIONAL POT HOLE COMING IN THE OPPOSITE DIRECTION, CLOSER TO BARLASTON ROAD

Enquiry No.: 4246465**Logged by:** CRM Connector**on:** 24/06/2021 08:12**Service:** Highway Operations**Subject:** CW Pothole**Classification:** Classified - Emergency**Desc.:** Road damage-Sinkhole

Date noticed 24 June 2021, This actually is pushing traffic in to the oncoming lane on a bend,

Approximate size (width, depth etc.)* - 15CM Approx

Location: Driving lane. Just on the bend heading towards Hidertone Level.**Contact:** [REDACTED]**Enquiry No.:** 4246464**Logged by:** CRM Connector**on:** 24/06/2021 08:10**Service:** Highway Operations**Subject:** CW Pothole**Classification:** Classified - Emergency**Desc.:** Road damage-Sinkhole

Date noticed 24 June 2021, Very Deep pothole,

Approximate size (width, depth etc.)* - 20CM - not safe to stop car so this approx size

Location: Driving lane. Just around the bend heading towards Longton Park**Contact:** [REDACTED]

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Customer Services

Enquiry No.: 4244780 **Logged by:** CRM Connector **on:** 10/06/2021 17:05
Service: Highway Operations **Subject:** CW Pothole **Classification:** General Enquiry
Desc.: Road damage-Pothole

Date noticed 09 June 2021, Large deep pothole.,

Approximate size (width, depth etc.)* - 800mm x 500mm x 150mm-175mm approx depth

Location: Driving lane. In carriageway on westbound side of road, just on bend in road near pond (just around bend from Report 4244779). **Contact:** [REDACTED]

Enquiry No.: 4244779 **Logged by:** CRM Connector **on:** 10/06/2021 17:00
Service: Highway Operations **Subject:** CW Pothole **Classification:** General Enquiry
Desc.: Road damage-Pothole

Date noticed 09 June 2021, A pothole to avoid, if you can!,

Approximate size (width, depth etc.)* - 750mm x 550mm x 125mm-150mm Approx depth

Location: Driving lane. East bound side of Cocknage Road near pond and bend in road. **Contact:** [REDACTED]

Enquiry No.: 4244044 **Logged by:** CRM Connector **on:** 05/06/2021 13:00
Service: Highway Operations **Subject:** CW Pothole **Classification:** General Enquiry
Desc.: Road damage-Edge failure

Date noticed 05 June 2021, Pothole in driving lane on left hand bend - drivers moving towards oncoming traffic to avoid.,

Approximate size (width, depth etc.)* - Several inches across & deep

Location: Driving lane. LH bend on Cocknage Road heading towards Rough Close - after junction with Barlaston Rd & before pond. **Contact:** [REDACTED]

Enquiry No.: 4205665 **Logged by:** CRM Connector **on:** 21/07/2020 08:01
Service: Highway Operations **Subject:** Drain Blocked Gully **Classification:** General Enquiry
Desc.: This relates to call Ref:4205494. The drain appears to be fully silted up

As a result my septic tank soakaway is backing up

PleeDe clear drain ASAP,

Location: outside my drive , [REDACTED] **Contact:** [REDACTED]

Plot Number: 1.00 **Feature Id - Location:** Driven **Feature Type:** Inspected Network
Defect Number: 1269727

Enquiry No.: 4205494 **Logged by:** CRM Connector **on:** 19/07/2020 12:32
Service: Highway Operations **Subject:** Drain Blocked Gully **Classification:** General Enquiry
Desc.: Drains and manholes-Blocked drain

Date noticed 01 June 2020, the drain is bloc led with debris, weeds are growing out of it and i believe the main drain is blocked,

Location: outside my drive , i live in [REDACTED] **Contact:** [REDACTED]

Plot Number: 1.00 **Feature Id - Location:** Driven **Feature Type:** Inspected Network
Defect Number: 1269727

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Customer Services

Enquiry No.: 4202126 **Logged by:** CRM Connector **on:** 18/06/2020 09:52
Service: Highway Operations **Subject:** CW Pothole **Classification:** General Enquiry
Desc.: This relates to call Ref:4196085. This hole forms part of a run of damage on an extremely busy and dangerous blind bend. Cars are now almost stopping when navigating this stretch, as the danger comes from not only vehicle damage but oncoming cars straying too far over the white line.,
Location: Kerb. Barlaston rd left hand side of a severe right hand bend, in the edge of a property?s driveway. **Contact:** [REDACTED]

Plot Number: 1.00 **Feature Id - Location:** Driven **Feature Type:** Inspected Network
Job Number: 2207815 **Defect Number:** 1266134

Enquiry No.: 4202121 **Logged by:** CRM Connector **on:** 18/06/2020 09:48
Service: Highway Operations **Subject:** CW Pothole **Classification:** General Enquiry
Desc.: This relates to call Ref:4196090. This hole forms part of a run of damage on an extremely busy and dangerous blind bend. Cars are now almost stopping when navigating this stretch, as the danger comes from not only vehicle damage but oncoming cars straying too far over the white line.,
Location: Cycle lane. Cocknage road, past the pond in the left side and approaching the severe right hand bend. These holes are on the left hand side of the carriageway. **Contact:** [REDACTED]

Plot Number: 1.00 **Feature Id - Location:** Driven **Feature Type:** Inspected Network
Job Number: 2207813 **Defect Number:** 1266131

Enquiry No.: 4196578 **Logged by:** CRM Connector **on:** 02/04/2020 16:22
Service: Highway Operations **Subject:** CW Pothole **Classification:** General Enquiry
Desc.: Road damage-Big pothole
Date noticed 02 April 2020, Pothole dangerous to cyclists and motorists a like.,
Approximate size (width, depth etc.)* - 18?x4?
Location: Cycle lane. Barlaston Rd past severe right hand bend. Hole is in the left lane of the carriageway **Contact:** [REDACTED]

Plot Number: 1.00 **Feature Id - Location:** Driven **Feature Type:** Inspected Network
Job Number: 2195690 **Defect Number:** 1257870

Enquiry No.: 4196090 **Logged by:** CRM Connector **on:** 23/03/2020 20:00
Service: Highway Operations **Subject:** CW Pothole **Classification:** General Enquiry
Desc.: Road damage-Pothole
Date noticed 23 March 2020, Severe erosion of road surface in several places within 20 feet,
Approximate size (width, depth etc.)* - 5 feet by several inches
Location: Cycle lane. Cocknage road, past the pond in the left side and approaching the severe right hand bend. These holes are on the left hand side of the carriageway. **Contact:** [REDACTED]

Plot Number: 1.00 **Feature Id - Location:** Driven **Feature Type:** Inspected Network
Job Number: 2198857 **Defect Number:** 1256041

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Customer Services

Enquiry No.: 4196085 **Logged by:** CRM Connector **on:** 23/03/2020 19:34
Service: Highway Operations **Subject:** CW Pothole **Classification:** General Enquiry
Desc.: Road damage-Edge failure

Date noticed 23 March 2020, Massive hole alongside a severe right hand bend, which is beginning to encroach onto the main carriageway. This is extremely dangerous if you have to pull into the left hand side of the road due to incoming traffic being in middle of the road, which very often happens.,

Approximate size (width, depth etc.)* - 5?x5? wise
8? deep

Location: Kerb. Barlaston rd left hand side of a severe right hand bend, in the edge of a property?s driveway.

Contact: [REDACTED]

Plot Number: 1.00 **Feature Id - Location:** Driven **Feature Type:** Inspected Network
Job Number: 2193998 **Defect Number:** 1249751

Enquiry No.: 4195765 **Logged by:** CRM Connector **on:** 18/03/2020 14:21
Service: Highway Operations **Subject:** FW/CY Debris **Classification:** Classified - Emergency
Desc.: Pavements-Debris

Date noticed 18 March 2020, I?ve had a call from the SCP Warden outside St Mathews Academy Rough Close to say following road works on Lightwood Road on the corner of Cocknage Road there is mud all over the footpath and crossing area where the Warden crosses Parents and Children. She said that it is very slippery and is concerned that someone will slip over. The mess over the footpath is where large vehicles have mounted the pavement to get around the corner during the roadworks. The roadworks have now been completed but the mess is still there. Please could you send someone to have a look to see what can be done. Thanks in advance for your time.,

Location: Lightwood Road Rough Close at the junction of Cocknage Road Close to St Mathews Primary Academy.

Contact: [REDACTED]

Plot Number: 1.00 **Feature Id - Location:** Driven **Feature Type:** Inspected Network
Job Number: 2198374 **Defect Number:** 1255393

Enquiry No.: 4185625 **Logged by:** CRM Connector **on:** 20/01/2020 14:53
Service: Highway Operations **Subject:** CW Pothole **Classification:** General Enquiry
Desc.: Road damage-Edge failure

Date noticed 20 January 2020, From photo you will see this large/deep hole is actually alongside the road. However it is on a very dangerous bend where cars often swerve to miss each other. If someone strays slightly off the road to the left there will be serious damage to and a loss of control of the vehicle.,

Approximate size (width, depth etc.)* - Several feet long and several inches deep

Location: Kerb. Left hand side of Cocknage Rd on sharp RH bend outside a property and field entrance.

Contact: [REDACTED]

Plot Number: 1.00 **Feature Id - Location:** Driven **Feature Type:** Inspected Network
Job Number: 2193998 **Defect Number:** 1249751

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Customer Services**Enquiry No.:** 4185180**Logged by:** CRM Connector**on:** 17/01/2020 08:24**Service:** Highway Operations**Subject:** CW Pothole**Classification:** Classified - Emergency**Desc.:** Road damage-Pothole

Date noticed 17 January 2020, Big hole.....,

Approximate size (width, depth etc.)* - Didn't stop to measure it, as it's a dangerous stretch of road. Probably about 12? Dia x 4? deep. It's big enough to cause an accident or damage to a vehicle

so needs attention

Location: Driving lane. It's big..... you can't miss it.**Contact:** [REDACTED]**Plot Number:** 1.00**Feature Id - Location:** Driven**Feature Type:** Inspected Network**Job Number:** 2137070**Defect Number:** 1248936**Enquiry No.:** 4181799**Logged by:** CRM Connector**on:** 18/12/2019 19:00**Service:** Highway Operations**Subject:** CW Pothole**Classification:** General Enquiry**Desc.:** Road damage-Edge failure

Date noticed 18 December 2019, The whole of cocknage Road needs looking at. The whole stretch is riddled with potholes and the edges of the road are disintegrated, barely wide enough for 2 normal sized cars to get past safely.,

Approximate size (width, depth etc.)* - Varying sizes, multiple holes. Way too many to do individually. I'd be out and sat here for hours plotting in every one.

Location: Driving lane. There's no more that 50m of road with no damage at all.**Contact:** [REDACTED]**Enquiry No.:** 4165483**Logged by:** Matt Weaver**on:** 22/07/2019 10:26**Service:** Highway Operations**Subject:** Drain Blocked Gully**Classification:** General Enquiry**Desc.:** caller reporting blocked drain**Location:** outside property called brae mar**Contact:****Plot Number:** 1.00**Feature Id - Location:** Driven**Feature Type:** Inspected Network**Job Number:** 2137070**Enquiry No.:** 4138326**Logged by:** CRM Connector**on:** 07/10/2018 12:44**Service:** Highway Operations**Subject:** CW Pothole**Classification:** General Enquiry**Desc.:** Road damage Potholes

Date noticed 7th October 2018, Hole at the side of the road, Approximate size (width, depth etc.) - 8in deep 2 ft long

Location: About 200 yds past Barlaston rd onto Cocknage rd going towards Rough Close common.**Contact:** [REDACTED]**Enquiry No.:** 4135554**Logged by:** CRM Connector**on:** 07/09/2018 09:14**Service:** Highway Operations**Subject:** CW Pothole**Classification:** General Enquiry**Desc.:** Road damage Potholes

Date noticed 7th September 2018, Deep pot hole, right where your off side wheel travels, Approximate size (width, depth etc.) - about two foot in diameter but deep

Location: From Barlaston Road going to Lightwood Road, before the left curve bend heading to common pond**Contact:** [REDACTED]

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Customer Services

Enquiry No.: 4129084 **Logged by:** [REDACTED] **on:** 28/06/2018 17:20
Service: Highway Operations **Subject:** CW Pothole **Classification:** General Enquiry
Desc.: Pothole which has split callers wheel and tyre
Location: If you come down the road from rough close towards longton park, it it as you come down the hill **Contact:**

Enquiry No.: 4120590 **Logged by:** CRM Connector **on:** 19/04/2018 15:11
Service: Highway Operations **Subject:** CW Pothole **Classification:** General Enquiry
Desc.: Road damage Potholes

Date noticed 29th March 2018, Large pothole filled with water on near side of road. Pothole caused front nearside tyre to be severely damaged and required replacement. Did not know about pothole until heard loud bang, another vehicle was approaching in the opposite direction at time of incident., Approximate size (width, depth etc.) - 28? length, 14? width, 6? depth
Location: Heading towards Meir Heath on Cocknage Road just after left hand bend and before approaching the pond. Cobble kirb stone and evidence of previous tarmac repair. Large SLOW sign on opposite side of road. **Contact:** [REDACTED]

Plot Number: 1.00 **Feature Id - Location:** Driven **Feature Type:** Inspected Network
Job Number: 2137070 **Defect Number:** 1248936

Enquiry No.: 4116093 **Logged by:** CRM Connector **on:** 28/03/2018 09:27
Service: Highway Operations **Subject:** CW Pothole **Classification:** General Enquiry
Desc.: Road damage Potholes

Date noticed 28th March 2018, pothole, Approximate size (width, depth etc.) - 7 inches deep and 1 meter long
Location: Near Address [REDACTED] outside heather **Contact:** [REDACTED]

Plot Number: 1.00 **Feature Id - Location:** Driven **Feature Type:** Inspected Network
Job Number: 2142104 **Defect Number:** 1187614

Enquiry No.: 4116053 **Logged by:** CRM Connector **on:** 27/03/2018 20:45
Service: Highway Operations **Subject:** CW Pothole **Classification:** General Enquiry
Desc.: Road damage Potholes

Date noticed 27th March 2018, 2 x big pothole, Approximate size (width, depth etc.) - 30cm x 30cm
Location: one on sharp left hand bend as you go downhill. one on sharp left hand bend as you go uphill just before pond **Contact:** [REDACTED]

Plot Number: 1.00 **Feature Id - Location:** Driven **Feature Type:** Inspected Network
Job Number: 2142103 **Defect Number:** 1187613

Enquiry No.: 4108235 **Logged by:** CRM Connector **on:** 16/02/2018 22:49
Service: Highway Operations **Subject:** CW Depression/Uneven **Classification:** General Enquiry
Desc.: Road damage Subsidence or cracking

Date noticed 15th February 2018, Really nasty cracking and road surface has full discintergrated at junction. No way of avoiding damage forcing vehicles to drive on verge,
Location: Junction of winterfield lane and hulme. Turning to hulme village **Contact:** [REDACTED]

Plot Number: 1.00 **Feature Id - Location:** Driven **Feature Type:** Inspected Network
Job Number: 2137070 **Defect Number:** 1248936

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Customer Services

Enquiry No.: 4087394 Logged by: [REDACTED] on: 27/07/2017 09:32
 Service: Highway Operations Subject: FW/CY Weed Growth Classification: General Enquiry
 Desc.: Ragwort growth overhanging the road
 Location: From Rose Cottage to Manor Lodge Farm Contact:

Enquiry No.: 4073388 Logged by: CRM Connector on: 06/03/2017 10:50
 Service: Highway Operations Subject: CW Pothole Classification: General Enquiry
 Desc.: Road damage Potholes

Date noticed 5th January 2017, Pothole in the road as you travel towards Barlaston Road.,
 Location: Approx 150 yards prior to Barlaston Road Contact: [REDACTED]

Plot Number: 1.00 Feature Id - Location: Driven Feature Type: Inspected Network
 Job Number: 2107511 Defect Number: 1151762

Enquiry No.: 4043192 Logged by: [REDACTED] on: 05/04/2016 15:43
 Service: Highway Operations Subject: CW Pothole Classification: General Enquiry
 Desc.: Two potholes at the end of his drive. Water constantly sitting on the road surface due to blocked drains. Please inspect. Also check drains and how well they are working. customer would also like to be contacted by inspector as this has been on going for over 12 months see ref 4010549
 Location: Outside Lane End, Cocknage Road. Contact:

Plot Number: 1.00 Feature Id - Location: Driven Feature Type: Inspected Network
 Job Number: 2084286

Enquiry No.: 4041992 Logged by: [REDACTED] on: 23/03/2016 14:14
 Service: Highway Operations Subject: Drain Blocked Gully Classification: General Enquiry
 Desc.: the grid has been blocked for a few months- at times with rain the drain keeps flooding.
 Location: Braemar, Cocknage Road, Rough Close Contact:

Plot Number: 1.00 Feature Id - Location: Driven Feature Type: Inspected Network

Enquiry No.: 4010549 Logged by: [REDACTED] on: 24/02/2015 15:19
 Service: Highway Operations Subject: Drain Blocked Gully Classification: General Enquiry
 Desc.: email received Road Issue - Road damage - Potholes

Approximate size (width, depth etc.)
 200 cm X 50 cm x15cm

Date first noticed
 25th September, 2014

Additional Information

The drains on cocknage road are blocked and so all the water is washing away the gutter. This has been happening since 1991. You have accepted liability for this and have kept patching the holes adjacent to the carriageway by my driveway. However the pot holes have now returned

Location: Easting:392377 Northing:339917 Contact:

Additional Location Information
 Potholes adjacent to lane End on cocknage road rough close Stoke on trent

Plot Number: 1.00 Feature Id - Location: Driven Feature Type: Inspected Network
 Job Number: 2035575 Defect Number: 1014205

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset:	1.00	Asset - Locn.: Driven	Feature Type: Inspected Network		Area: S - Stone Rural North		
2014867	Cutting back trees that are overhanging the highway on Cocknage Road Length:80m Height:-1mm Area:0m2	Opposite the common and just above the pool	Cat 4: No Time Constraint	No Longer Required by Client	16/05/2014		
2031336	Cut out & patch 2x 1sqm (CW Pothole)	On bend Os heather lodge	Cat 3: 28 Days From Insp	Job Closed and Archived	16/04/2015	12/05/2015	Act. HWSCC/5020246
2033798	Patch required 0.5mtrx0.5mtrx45mm ***WET NOT MARKED*** (CW Pothole)	On bad bend outside heather lodge	Cat 3Q: 45 Days From Insp	Job Closed and Archived	07/05/2015	12/05/2015	Act. HWSCC/5022621
2033799	Patch required on carraigeway edge pothole 1mtr2 80mm ***WET NOT MARKED*** ***TOO DANGEROUS FOR PHOTOS*** (CW Pothole)	On bad bend opposite heather lodge above slow road marker	Cat 2: 7 Days From Insp	Job Closed and Archived	07/05/2015	12/05/2015	Act. HWSCC/5022622
2035575	clear and jet all gullies and manholes including any offlets, prove all outlets are clear from jct A5005 Lightwood Road to Stoke City Boundary also make sure all set back gullies are cleared there are some near to jct A5005	from jct of lightwood road to Stoke city boundary	Cat 3: 28 Days From Insp	Contractor Completed	26/05/2015	02/11/2015	Act. HWSCC/5024358
2035579	DRAIN Gully Emptying - email reicved Road Issue - Road damage - Potholes Approximate size (width, depth etc.) 200 cm X 50 cm x15cm Date first noticed 25th September, 2014 Additional Information The drains on cocknage road are blocked and so all the water is washing away the gutter. This has been happening since 1991. You have accepted liability for this and have kept patching the holes adjacent to the carriageway by my driveway. However the pot holes have now returned (Enquiry 4010549)	Easting:392377 Northing:339917 Additional Location Information Potholes adjacent to lane End on cocknage road rough close Stoke on trent	Cat 3: 28 Days From Insp	Job Cancelled	26/05/2015		

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset:	1.00	Asset - Locn.: Driven	Feature Type: Inspected Network		Area: S - Stone Rural North		
2083407	Replace 75mm diameter post standing approx 4 foot out of the ground. Transfer existing severe deviation chevron board to new post and existing. Chevron board still on site. (ULTS Damaged)	On bend opposite pool.	Cat 3Q: 45 Days From Insp	Contractor Completed	12/05/2016	01/06/2016	Act. HWSCC/5057662
2084284	remove surface dressing from around gully frame then make sure gully top can be removed once sorted try and remove some silt from pot so jetter can clear and jet after	o/s church house on right hand side of drive	Cat 3: 28 Days From Insp	Contractor Completed	20/05/2016	12/07/2016	Act. HWSCC/5058559
2084285	clear and jet all gullies from Church House also try and lightly jet pipe which goes under the drive of Lane End then continue down the road also check and clear any that are buried in edge of verges Report any problem which might require further work NOTE [REDACTED] to be contact 48hrs before work commences	starting o/s church house first on RHS of drive	Cat 3: 28 Days From Insp	Contractor Completed	20/05/2016	25/06/2019	Act. HWSCC/5058560
2084286	patch along edge of carriageway across the drive of lane end incorporating a small width of drive but care to be taken with roller due to the condition of this drive and try and not form a valley so water holds complaint from resident it ponds here due to potholes etc	across drive of lane end	Cat 3: 28 Days From Insp	Contractor Completed	20/05/2016	08/05/2017	Act. HWSCC/5058561
2107511	Cut and patch pothole marked. Approximately 0.5sqm (CW Pothole)	By the chevron signs just past Heather lodge.	Cat 2: 7 Days From Insp	Contractor Completed	07/03/2017	14/03/2017	Act. HWSCC/5080988
2120784	Replace cross roads sign ref 504-1 for SIZE 750MM (ULTS Dirty/Worn)	50m rom Lightwood road	Cat 3Q: 45 Days From Insp	Contractor Completed	11/08/2017	13/10/2017	Act. HWSCC/5093734
2120785	Mechanical road sweeper required to remove loose gravel (CW Debris)	Befor double chevron bend at Stoke boundry to bends sign	Cat 3Q: 45 Days From Insp	Contractor Completed	11/08/2017	08/12/2017	Act. HWSCC/5093735
2137070	Highway Carriageway Repairs - T3 Wet not marked. (GPS not working). (CW Pothole)	Just before access to Heather Lodge on lower side of access but on opposite side of carriageway.	Cat 3Q: 45 Days From Insp	Completed - Crew	15/02/2018	17/02/2020	Act. HWSCC/5165241

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Driven		Feature Type: Inspected Network		Area: S - Stone Rural North	
2137071	Replace 1 x missing post 80mm in diameter and 1 x missing severe deviation board sign face fig no. 515. Sign face measures 1.20m x 0.40m (ULTS Missing/Broken)	On outside of bend opposite pond. (NOTE GPS not working).	Cat 3Q: 45 Days From Insp	Contractor Completed	15/02/2018	30/04/2018	Act. HWSCC/5109067
2142103	Fill the carriageway pothole, not marked due to the location. Approximately 1sqm (CW Pothole)	Outside Heather cottage, opposite the slow road marking.	Cat 1: 24 Hours From Insp	Contractor Completed	10/04/2018	11/04/2018	Act. HWSCC/5113786
2142104	Fill the carriageway pothole, not marked due to the location. Approximately 0.5sqm (CW Pothole)	outside heather lodge, by the chevrons	Cat 1: 24 Hours From Insp	Contractor Completed	10/04/2018	11/04/2018	Act. HWSCC/5113787
2153980	Cut back hedgerow obscuring give way sign. Pole shears required here. (TRHE Obscuring Street Furn)	At junction with Lightwood Road.	Cat 3Q: 45 Days From Insp	Contractor Completed	14/08/2018	18/10/2018	Act. HWSCC/5125185
2181339	Cut back hedgerow from around give way warning sign so thst sign can be seen on approach to the junction. Pole shears required here. (TRHE Obscuring Street Furn)	By Church House st junction with Lightwood Road.	Cat 3Q: 45 Days From Insp	Contractor Completed	15/08/2019	21/08/2019	Act. HWSCC/5151505
2182143	FOR INFO ONLY, TREE SURGEON ATTENDED AT 2AM ON 27TH AUGUST TO REMOVE FALLEN TREE, INCIDENT 34 (rob keysor) (OOH Other)	Near lightwood road	Emergency: 2 Hours From Insp	Contractor Completed	27/08/2019	27/08/2019	Act. HWSCC/5152276
2188507	Highway Drainage Investigation - Dig down in verge and replace broken 7inch salt glazed highway drainage pipe. Cone has been placed over by Inspector to warn/guard. (DRAIN Other)	Opposite gates to property called Church House approx 40 metres from jct with Lightwood Road.	Cat 3M: 28 Days From Insp	Job - Available for Scheduling	13/11/2019	31/03/2021	Est. HWSCC/5170051
2188508	FOR INFO ONLY - broken highway drain in verge, Inspector has plscd cone over to warn/guard until pipe can be replaced. (DRAIN Other)	In verge opposite gates to property called Church House approx 40 metres from jct with Lightwood Road.	Emergency: 2 Hours From Insp	Contractor Completed	13/11/2019	13/11/2019	Act. HWSCC/5158185
2193998	Highway Carriageway Repairs - T3 x1 (CW Pothole)	In the vehicular access to the property called Heather lodge	Cat 3: 28 Days From Insp	Completed - Already Complete	24/01/2020	04/08/2020	Act. HWSCC/5165641
2195690	Highway Carriageway Repairs - T3 X 2. Wet not marked. (CW Pothole)	Travelling towards Cocknage located on left just after access to Heather Lodge before chevron boards.	Cat 3Q: 45 Days From Insp	Completed - Already Complete	13/02/2020	04/08/2020	Act. HWSCC/5169349

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset:	1.00	Asset - Locn.: Driven	Feature Type: Inspected Network		Area: S - Stone Rural North		
2195691	Highway Carriageway Repairs - T3. This job supersedes existing job number 2137070. (CW Pothole)	Travelling towards Rough Close and situated on left on inside of bend just past access to Heather Lodge.	Cat 2: 7 Days From Insp	Completed - Crew	13/02/2020	17/02/2020	Act. HWSCC/5165240
2195692	Highway Carriageway Repairs - T3 Type 3. X 1. Wet not marked. (CW Pothole)	In centre of road just below access to Heather Lodge.	Cat 3Q: 45 Days From Insp	Completed - Already Complete	13/02/2020	04/08/2020	Act. HWSCC/5169348
2198374	FOR INFORMATION ONLY- Highway Footway Cleansing Works - 18/03/20, time of completion 18:30hrs, Inspector cleared away over ridden mud/verge from footway and hand swept footway. (FW/CY - Debris)	Crossing point footway cocknage road side of lightwood road	Cat 2: 7 Days From Insp	Completed - Already Complete	19/03/2020	18/03/2020	Act. HWSCC/5175316
2198857	Highway Carriageway Repairs - Type 3 (CW - Pothole)	Just after the slow road markings by the property called heather lodge	Cat 3: 28 Days From Insp	Completed - Already Complete	24/03/2020	04/08/2020	Act. HWSCC/5176215
2207813	Highway Carriageway Repairs - Type 3 x4 This job supersedes job no 2195690. (CW - Pothole)	Approximately 10m before the property called heather lodge	Cat 2: 7 Days From Insp	Completed - Crew	22/06/2020	23/06/2020	Act. HWSCC/5189173
2207815	Highway Carriageway Repairs - Type 3 x2 (CW - Pothole)	Approximately 10m after the entrance to the property called heather lodge	Cat 2: 7 Days From Insp	Completed - Crew	22/06/2020	23/06/2020	Act. HWSCC/5189174
2212108	Highway Carriageway Repairs - T3 x 1. This job supersedes existing job number 2193998. (Job 1 of 2). (CW - Edge Failure)	In VAC to property called Heather Lodge.	Cat 2: 7 Days From Insp	Completed - Crew	31/07/2020	04/08/2020	Act. HWSCC/5193292
2212109	Highway Carriageway Repairs - T3 x 1. This job supersedes existing job number 2193998. (Job 2 of 2). (CW - Edge Failure)	In VAC to property called Heather Lodge.	Cat 2: 7 Days From Insp	Completed - Crew	31/07/2020	04/08/2020	Act. HWSCC/5193293
2212110	Highway Road Marking Repairs - refresh slow road marker. (RMark - Worn)	On lowerside of access to property called Heather Lodge.	Cat 4: No Time Constraint	Completed - Crew	31/07/2020	03/02/2023	Act. HWSCC/5193311
2220367	Highway Carriageway Repairs - Type 2 (CW - Pothole)	5 mtrs before slow marked on road	Cat 3Q: 45 Days From Insp	Completed - Already Complete	05/11/2020	23/07/2026	Act. HWSCC/5201923
2220368	Highway Carriageway Repairs - Type 2 (CW - Pothole)	Opposite access 5 mtrs before double bend sign	Cat 3Q: 45 Days From Insp	Completed - Crew	05/11/2020	06/12/2024	Act. HWSCC/5201924

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset:	1.00	Asset - Locn.: Driven	Feature Type: Inspected Network		Area: S - Stone Rural North		
2228019	Highway Signage Repairs - replace a displaced 76mm post standing approx 1.5 metres out of the ground. Replace 2 x securing bands and fasten severe deviation board to new post. Remove old post with lump of concrete on the base from site. Inspector has placed a cone at base of old post to warn/guard. (TS - Damaged/Missing)	On outside of bend opposite pool.	Cat 2: 7 Days From Insp	Completed - Crew	28/01/2021	04/02/2021	Act. HWSCC/5209629
2239347	Highway Signage Maintenance - clean graffiti off severe deviation chevron board. (TS - Graffiti/Dirty)	Approx 264 metres west of junction with Lightwood Road opposite pond.	Cat 3Q: 45 Days From Insp	Completed - Crew	12/05/2021	01/07/2022	Act. HWSCC/5220682
2239348	Highway Carriageway Repairs - T3 (CW - Cracking/Cracking)	Opposite pool approx 311 metres from junction with the A5055 Lightwood Road travelling towards Cocknage from Rough Close.	Cat 3Q: 45 Days From Insp	Completed - Crew	12/05/2021	10/09/2024	Act. HWSCC/5220683
2257817	Highway Carriageway Repairs - Type 3 please repair x4 carriageway potholes and associated cracking and fretting (CW - Pothole)	Just before entrance to Heather Lodge, 6 metres after Chevron Signs and x3 opposite Heather Lodge close to SLOW road markings	Cat 3Q: 45 Days From Insp	Completed - Crew	22/10/2021	04/10/2024	Act. HWSCC/5238990
2257818	Highway Carriageway Repairs - Type 3 please repair x5 carriageway potholes and associated cracking and fretting (CW - Pothole)	From outside property called Oakhurst up to property called Southbank on LHS of the carriageway heading towards the A5005	Cat 3Q: 45 Days From Insp	Completed - Crew	22/10/2021	11/09/2024	Act. HWSCC/5238991
2266857	Highway Carriageway Repairs - Type 3, CAT2, please repair x1 carriageway pothole This job supersedes in part existing job number 2257817 (CW - Pothole)	Opposite property called Heather Lodge, 10 metres after Heather Lodge driveway, at end of kerb setts, on LHS of the carriageway heading towards Cocknage Wood	Cat 2: 7 Days From Insp	Completed - Crew	20/01/2022	25/01/2022	Act. HWSCC/5248261
2278178	Highway Carriageway Repairs - Type 3, CAT2, please repair x1 carriageway pothole. This job supersedes in part, existing job number 2257818 (CW - Pothole)	Outside property called Southbank	Cat 2: 7 Days From Insp	Completed - Crew	09/05/2022	13/05/2022	Act. HWSCC/5259876
2285634	Highway Carriageway Repairs - T4 (CW - Pothole)	Opposite pond by pull in parking area for Barlaston and Rough Close Common Local Nature Reserve.	Cat 3Q: 45 Days From Insp	Completed - Crew	22/07/2022	09/09/2024	Act. HWSCC/5909185

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset:	1.00	Asset - Locn.: Driven	Feature Type: Inspected Network		Area: S - Stone Rural North		
2300655	Highway Carriageway Repairs - T3. This job partsupersedes existing job number 2257817. (CW - Pothole)	Slightly on lowerside of access to Heather Lodge.	Cat 2: 7 Days From Insp	Completed - Crew	27/01/2023	31/01/2023	Act. HWSGCC/5275943
2309460	Highway Carriageway Repairs - T2. Renew give way lines to be patched over. (CW - Pothole)	On give way l8nes at the junction with Lightwood Road.	Cat 3Q: 45 Days From Insp	Completed - Crew	11/05/2023	12/09/2024	Act. HWSGCC/5282985
2317648	Highway Carriageway Repairs - T4 x 1 (CW - Pothole)	Opposite pool approx 311 metres from junction with the A5055 Lightwood Road travelling towards Cocknage from Rough Close.	Cat 1: 24 Hours From Insp	Completed - Crew	08/08/2023	09/08/2023	Act. HWSGCC/5290144
2328086	Highway Carriageway Repairs - T4 adjacent a flooded gulley. (CW - Pothole)	Travelling towards Cocknage and located on the left just before the culverted water course.	Cat 2: 7 Days From Insp	Completed - Crew	18/12/2023	11/01/2024	Act. HWSGCC/5298810
2329904	Highway Carriageway Repairs - T4 adjacent blocked gulley. Road is being damaged by blocked gulley not draining surface water away. Cones placed to warn/guard. This job supersedes existing job number 2328086. (CW - Pothole)	Adjacent blocked gulley just before fencing to culverted water course.	Cat 1: 24 Hours From Insp	Completed - Crew	11/01/2024	12/01/2024	Act. HWSGCC/5300351
2329905	Highway Carriageway Repairs - T4 (CW - Pothole)	Just before fencing to culverted water course.	Cat 1: 24 Hours From Insp	Completed - Crew	11/01/2024	11/01/2024	Act. HWSGCC/5300352
2329906	Highway Carriageway Repairs - T3. To wet to mark. (CW - Crazing/Cracking)	Around gulley by culverted water course.	Cat 3: 28 Days From Insp	Completed - Crew	11/01/2024	13/09/2024	Act. HWSGCC/5300745
2356270	Highway Carriageway Repairs - T4 (CW - Pothole)	20m prior to bridge area	Cat 1: 24 Hours From Insp	Completed - Crew	01/08/2024	01/08/2024	Act. HWSGCC/5326197
2367364	Highway Signage Repairs - reset leaning post and reattach chevron board back onto posts. (TS - Misaligned/Loose)	On outside of bend opposite Pool.	Cat 3Q: 45 Days From Insp	Completed - Crew	25/10/2024	15/08/2025	Act. HWSGCC/5337346
2387378	Highway Carriageway Repairs - T3 (CW - Pothole)	On inside edge of bend by pool.	Cat 3Q: 45 Days From Insp	Completed - Already Complete	28/04/2025	23/07/2026	Act. HWSGCC/5357191
2387381	Highway Carriageway Repairs - T3 (CW - Pothole)	On inside of bend just up from access to Heather Lodge. Opposite severe deviation chevron boards.	Cat 1: 24 Hours From Insp	Further work- Diff Crew	28/04/2025	28/04/2025	Act. HWSGCC/5357193
2387388	Highway Carriageway Repairs - T3 x 5 (CW - Pothole)	On both the upper and lowerside of the access to Heather Lodge.	Cat 3Q: 45 Days From Insp	Completed - Already Complete	28/04/2025	10/10/2025	Act. HWSGCC/5357200
2387389	Highway Road Marking Repairs - SCREED - refresh all give way markings including triangle road marker. (RMark - Worn)	At jct with Lightwood Road.	Cat 3Q: 45 Days From Insp	Completed - Crew	28/04/2025	01/05/2025	Act. HWSGCC/5357201

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset:	1.00	Asset - Locn.: Driven	Feature Type: Inspected Network		Area: S - Stone Rural North		
2403910	Highway Carriageway Repairs - T3 This job supercedes existing job number 2387388 (CW - Pothole)	Approximately 10 meters downhill from the property called Heather Lodge	Cat 1: 24 Hours From Insp	Completed - Crew	09/10/2025	10/10/2025	Act. HWSGCC/5373815
2406108	Pre-Surface Dressing -6537 2026works patching required (CW - Crazing/Cracking) 331 m2	From A5005 lightwood road to stoke city boundary (bend by Heather Lodge	Annual Planned Works	Completed - Crew	30/10/2025	01/05/2026	Act. HWSGCC/5376013
2408432	Highway Carriageway Repairs - T3 Please cut and patch marked area, consisting of potholes and adjacent crazing and cracking. (CW - Pothole)	Approximately 20 meters east from access to property called Rose Cottage	Cat 3: 28 Days From Insp	Completed - Already Complete	25/11/2025	23/07/2026	Act. HWSGCC/5378326
2408434	Highway Carriageway Repairs - T4 Please make safe until permanent Repairs will be carried out under job number 2408432 (CW - Pothole)	Approximately 30 meters east from access to property called Rose Cottage	Cat 1: 24 Hours From Insp	Completed - Crew	25/11/2025	26/11/2025	Act. HWSGCC/5378328
2427419	Highway Carriageway Repairs - T4 Please make good area marked Job 1 of 6 (CW - Pothole)	20m past vac to rose cottage on the right	Cat 1: 24 Hours From Insp	Completed - Crew	21/04/2026	21/04/2026	Act. HWSGCC/5397289
2427422	Highway Carriageway Repairs - T4 Please make good area marked Job 2 of 6 (CW - Pothole)	20m past vac to rose cottage on the right	Cat 1: 24 Hours From Insp	Completed - Crew	21/04/2026	22/04/2026	Act. HWSGCC/5397292
2427425	Highway Carriageway Repairs - T4 Please make good area marked Job 3 of 6 (CW - Pothole)	20m past vac to rose cottage on the right	Cat 1: 24 Hours From Insp	Completed - Crew	21/04/2026	22/04/2026	Act. HWSGCC/5397295
2427426	Highway Carriageway Repairs - T4 Please make good area marked Job 4 of 6 (CW - Pothole)	20m past vac to rose cottage on the right	Cat 1: 24 Hours From Insp	Completed - Crew	21/04/2026	22/04/2026	Act. HWSGCC/5397297
2427427	Highway Carriageway Repairs - T4 Please make good area marked Job 5 of 6 (CW - Pothole)	20m past vac to rose cottage on the right	Cat 1: 24 Hours From Insp	Completed - Crew	21/04/2026	22/04/2026	Act. HWSGCC/5397298
2427428	Highway Carriageway Repairs - T4 Please make good area marked Job 6 of 6 (CW - Pothole)	20m past vac to rose cottage on the right	Cat 1: 24 Hours From Insp	Completed - Crew	21/04/2026	22/04/2026	Act. HWSGCC/5397299
2427432	Highway Carriageway Repairs - T4 (CW - Pothole)	40m past vac to rose cottage on the right	Cat 1: 24 Hours From Insp	Completed - Crew	21/04/2026	21/04/2026	Act. HWSGCC/5397303

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Driven		Feature Type: Inspected Network		Area: S - Stone Rural North	
2429207	Pre-Surface Dressing-site 6537 ROADMASTER WORKS AS REQUIRED ROAD CLOSURE USING 15MIN DELAY SIGNS MOBILE WORKS (CW - Cracking/Cracking)	From A5005 lightwood rd to bend by Heather Lodge	Annual Planned Works	Completed - Already Complete	30/04/2026	25/08/2026	Act. HWSCC/5412609
2429446	Pre-Surface Dressing-site 6537 ROADMASTER WORKS AS REQUIRED ROAD CLOSURE USING 15MIN DELAY SIGNS MOBILE WORKS (CW - Cracking/Cracking) (CW - Cracking/Cracking)	From A5005 lightwood rd to bend by Heather Lodge	Annual Planned Works	Completed - Crew	05/05/2026	06/05/2026	Act. HWSCC/5399315
2439895	Highway Road Marking Repairs - Repaint worn SLOW markings (RMark - Worn)	18mtrs south of access to Heather Lodge	Cat 3Q: 45 Days From Insp	Completed - Already Complete	23/07/2026	25/08/2026	Act. HWSCC/5409756
8139758	as marked, make safe with recycled material	v.a to braemar	Cat 3M: 28 Days From Insp	Job Closed and Archived	19/09/2012	06/11/2012	Act.
8161028	REPAINT WORN GIVE WAY LINES, TRIANGLE AND BROKEN WHITE CENTRE LINES UP TO THE JUNCTION.	AT THE JUNCTION WITH LIGHTWOOD ROAD.	Cat 3A: 60 Days From Insp	Job Closed and Archived	20/09/2012	13/11/2012	Act.
8161029	REPLACE 3 X GALVANISED TUBULAR STEEL RAILS. EACH RAIL SHOULD MEASURE 5.20 METRES LONG.	OVER CULVERT JUST BEFORE DISTRICT BOUNDARY.	Cat 3A: 60 Days From Insp	Job Closed and Archived	20/09/2012	22/10/2013	Act.
8162622	PLANE OUT AND PATCH POTHLES AND UNEVEN ROAD SURFACE WHERE MARKED ON SITE.	ON INSIDE OF BEND BY POOL.	Cat 3Q: 45 Days From Insp	Job Closed and Archived	26/10/2012	08/11/2012	Act.
8173187	NOT MARKED, NEXT TO OLD TRENCH	CLOSE TO JUNC, GIVE WAY	Cat 3Q: 45 Days From Insp	Job Closed and Archived	08/05/2013	19/08/2013	Act.
8193878	REPAIR POTHOLE X 1.	ON GIVE WAY JUNCTION WITH LIGHTWOOD ROAD.	Cat 3Q: 45 Days From Insp	Job Closed and Archived	07/08/2013	19/08/2013	Act.
8193879	REPAIR 4 X POTHLES WHERE MARKED ON SITE. STOP/GO REQD HERE WITH WALKY TALKIES DUE TO BEND IN ROAD.	OUTSIDE PROPERTY CALLED HEATHER LODGE ON BEND AND BOUNDARY WITH STOKE ON TRENT COUNCIL.	Cat 2: 7 Days From Insp	Job Closed and Archived	07/08/2013	12/08/2013	Act.
8193880	SCREED - REFRESH WHITE SLOW ROAD MARKER.	ON BEND OUTSIDE PROPERTY CALLED HEATHER LODGE.	Cat 3Q: 45 Days From Insp	Job Closed and Archived	07/08/2013	11/09/2013	Act.
8203049	CLEAN CROSS ROADS SIGN	75M BEFOR LIGHTWOOD ROAD	Cat 3Q: 45 Days From Insp	Job Closed and Archived	07/02/2013	01/03/2013	Act.
8210618	confirmation of works by c.o.c 01/02/14 2x slippery road boards out	on bad bend	Emergency: 2 Hours From Insp	Job Closed and Archived	04/02/2014	04/02/2014	Act.

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Driven	Feature Type: Inspected Network		Area: S - Stone Rural North		
8210795	collect 2x slippery road boards	on bends, rough close end	Cat 2: 7 Days From Insp	Job Closed and Archived	04/02/2014	17/02/2014	Act.
8220623	SCREED - REPLACE MISSING GIVE WAY LINES WHICH HAVE BEEN PATCHED OVER.	AT THE JUNCTION WITH LIGHTWOOD ROAD.	Cat 3Q: 45 Days From Insp	Job Closed and Archived	29/01/2014	10/02/2014	Act.
8224159	FILL POTHOLE ON INSIDE OF BEND	COCKNAGE ROAD BEND FROM LIGHWOOD RD	Cat 1: 24 Hours From Insp	Job Closed and Archived	01/08/2014	01/08/2014	Act.
8224629	REPAIR POTHOLE	OS SOUTHBANK MARKED	Cat 3Q: 45 Days From Insp	Job Closed and Archived	14/05/2014	02/06/2014	Act.
8224630	PATCH MARKED FROM GULLY 25M2 NOTE POTHLE TEMP FILLED CAT 1 .	ON BEND OPPOSITE THE POOL	Cat 3Q: 45 Days From Insp	Job Closed and Archived	14/05/2014	05/08/2014	Act.
8224631	TEMP FILL POTHOLE 1.5M 100MM DEPTH 2 PHOTOS TPCN PASSED TO PB 15.00PM	ON BEND OPPSITE POOL MARKED	Cat 1: 24 Hours From Insp	Job Closed and Archived	14/05/2014	15/05/2014	Act.
8224632	REMARK CARRIAGEWAY CENTRE LINE	FROM STOKE BOUNDRY TO LIGHTWOOD ROAD	Cat 3Q: 45 Days From Insp	Job Closed and Archived	14/05/2014	30/06/2014	Act.
Asset: 10,004.00		Asset - Locn.: 151883	Feature Type: Drainage Asset - Gully		Area: S - Stone Rural North		
30010362	Highway Ironwork Repairs - Ironwork to be replaced and brickwork if needed - CW - Gully Lid Jammed	before pond before the bend	Cat 3: 28 Days From Insp	Completed - Crew	18/05/2021	04/12/2025	Act. HWSGCC/5907461
Asset: 10,005.00		Asset - Locn.: 151884	Feature Type: Drainage Asset - Gully		Area: S - Stone Rural North		
2300654	Highway Ironwork Repairs - reset loose gully where marked. (CW - Ironwork Loose/Rocking)	Opposite pool approx 311 metres from junction with the A5055 Lightwood Road travelling towards Cocknage from Rough Close.	Cat 3Q: 45 Days From Insp	Completed - Crew	27/01/2023	05/12/2025	Act. HWSGCC/5275942
2406102	Pre-Surface Dressing 6537 2026 Works - Reset Grid (CW - Ironwork Loose/Rocking)	Just down from lay-by	Annual Planned Works	Completed - Crew	30/10/2025	05/12/2025	Act. HWSGCC/5376007
Asset: 10,006.00		Asset - Locn.: 151885	Feature Type: Drainage Asset - Gully		Area: S - Stone Rural North		
2328073	Highway Ironwork Repairs - replace defective gully with jammed lid. (CW - Ironwork Defective)	Travelling towards Cocknage and located on the left just before the culverted water course.	Cat 3: 28 Days From Insp	Job Cancelled	18/12/2023	08/01/2024	Est. HWSGCC/5298978
2328074	Highway Drainage Works - empty and jet blocked gully. (Blocked Gully Wagon Required)	Travelling towards Cocknage and located on the left just before the culverted water course.	Cat 3: 28 Days From Insp	Held - Phased Delivery	18/12/2023	15/01/2024	Est. HWSGCC/5298811
30010365	Highway Drainage Works - Ensure lift if unable to lift replace ironwork as well as brick work if needed - CW - Gully Lid Jammed	Just past pond	Cat 3: 28 Days From Insp	Job - Scheduled for Delivery	18/05/2021	04/11/2026	Est. HWSGCC/5907730

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 10,008.00	Asset - Locn.: 151926		Feature Type: Drainage Asset - Gully		Area: S - Stone Rural North	
30010363	Blocked Gully Wagon Required	Outside the property called Braemar.	No Code Allocated	Completed - Crew	18/05/2021	18/05/2021	Act.
30010364	Highway Drainage works - Clean and jet gully Blocked Jetting Required	Outside Oakhurst	Cat 3: 28 Days From Insp	Completed - Crew	18/05/2021	04/11/2024	Act. HWSGCC/5907512

Street Works Inspections

Organisation: 5123 Stoke Central (7011523)					
Works Ref: M51231952541B					
Group No: 1	Site No: 1	Street Authority: STAFFORDSHIRE COUNTY COUNCIL		Inspected: 24/08/2016 11:52:24	
Category: Category A		Outcome: Passed		Sampled: No	
Defect Notif. No: N/A		Defect No: N/A		Site Informed: Yes	
		Tel: 07896281260		Site Location: Side of Church House	
Insp. Notes:				Position: Not Known (Position)	
Defect Notes:				Sign./Light./Guard. Inadequacy: No	
Sampled Site No:					
Site Post Code:					
Organisation: BT (0030005)					
Works Ref: WP00400500266308500					
Group No: 1	Site No: 1	Street Authority: STAFFORDSHIRE COUNTY COUNCIL		Inspected: 23/08/2018 14:58:37	
Category: Category A		Outcome: Abortive		Sampled: No	
Defect Notif. No: N/A		Defect No: N/A		Site Informed: Yes	
		Tel: 07773791431		Site Location: (PCP33) SIDE OF HEATHER LODGE, COCKNAGE ROAD	
Insp. Notes:				Position: Verge	
Defect Notes:				Sign./Light./Guard. Inadequacy: No	
Sampled Site No:					
Site Post Code:					
Organisation: Highways Reactive (3450111)					
Works Ref: 2403910ETW					
Group No: 1	Site No: 1	Street Authority: STAFFORDSHIRE COUNTY COUNCIL		Inspected: 28/11/2025 13:09:20	
Category: Non Categorised Inspection		Outcome: Passed		Sampled: No	
Defect Notif. No: N/A		Defect No: N/A		Site Informed: Yes	
		Tel:		Site Location: (carriageway)Approximately 10 meters downhill from the property called Heather Lodge	
Insp. Notes:				Position: Not Known (Position)	
Defect Notes:				Sign./Light./Guard. Inadequacy: No	
Sampled Site No:					
Site Post Code:					

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Street Works Inspections

Organisation: Highways Recovery (3450112)				
Works Ref: 2329906RCHRP				
Group No: 1	Site No: 1	Street Authority: STAFFORDSHIRE COUNTY COUNCIL	Inspected: 10/09/2024 13:59:36	
Category: Category A		Outcome: Failed (Lower Risk/Non Dangerous)	Sampled: No	Sampled Site No:
Defect Notif. No: 1054467		Defect No: 1054467	Site Informed: Yes	Sign./Light./Guard. Inadequacy: No
		Tel: 07976890401	Site Location: Whole of USRN	
Insp. Notes:	Inspection of Category - A is converted to Routine due to - 'The target for category A inspections has already been reached'. The sign lighting and guarding has not met the minimum standards required two way signals being used without the 1.2 metres sideways safety zone and barriers around work site, notice states should be a road closure , noted repairs large and vibro plate not sufficient for compaction of surface course hand ped roller would be more suitable, also of note gully compacted where area to be repaired and further road damage being left up to new repair, team leader t.hassall informed via phone		Position: Not Known (Position)	Site Post Code:
Defect Notes:	The sign lighting and guarding has not met the minimum standards required two way signals being used without the 1.2 metres sideways safety zone and barriers around work site, notice states should be a road closure , noted repairs large and vibro plate not sufficient for compaction of surface course hand ped roller would be more suitable, also of note gully compacted where area to be repaired and further road damage being left up to new repair, team leader t.hassall informed via phone			

Organisation: STW Water West (9103914)									
Works Ref: 1202/000010483960									
Group No: 1		Site No: 1		Street Authority: STAFFS CC (STAFFORD AREA W1)			Inspected: 17/11/2014 11:54:00		
Category: Category C				Outcome: Passed			Sampled: Yes		Sampled Site No: 1
Defect Notif. No: N/A				Defect No: N/A			Site Informed: No		Sign./Light./Guard. Inadequacy: No
				Tel:			Site Location: OPP. OAKHURST COCKNAGE ROAD ROUGH CLOSE STAFFORDSHIRE COUNTY COUNCIL		
Insp. Notes: [REDACTED]							Position: Verge		Site Post Code:
Defect Notes:									

Last Inspection update received on: 17/11/2014 12:00:26

Street Works Notices

Organisation: 5123 Stoke Central (7011523)										
Works Ref: M51231952541B			Version: 5		Work Desc: Traffic Light Head Only - No Excavation					
Notice Type: Works Stop			Start: 22/08/2016 00:00:00							
Work Status: Works Stopped			Issued: 31/08/2016 15:22:06							
Work Type: EToN 4: Standard			Est. End: 26/08/2016		Completion: 26/08/2016					
Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Side of Church House	Not Known (Position)	Not Known (Depth)	0.00	0.00	Site Closed (No Excavation)	26/08/2016			26/08/2016
Organisation: BT (0030005)										
Works Ref: WP00400500266308500			Version: 4		Work Desc: Build 1 concrete chamber 1310mm x 610mm x 1265mm deep in Footway,Install 1m of 1 way poly duct in Verge					
Notice Type: Registration of Reinstatement - Full			Start: 20/08/2018 00:00:00							
Work Status: Works Stopped			Issued: 06/09/2018 09:56:22							
Work Type: EToN 4: Minor			Est. End: 22/08/2018		Completion: 22/08/2018					
Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	(PCP33) SIDE OF HEATHER LODGE, COCKNAGE ROAD	Verge	Up to 1.5 Metres of Cover	1.00	0.40	A Permanent Reinstatement	22/08/2018		22/08/2018	22/08/2018

Effective: 10/09/2012 to 10/09/2026

Service: Highway Operations

Display Action Officer: No

Site: COCKNAGE ROAD (37601017)

Street Works Notices

Organisation: BT: OR DL (0030008)										
Works Ref: WDKDVC1P02 Notice Type: Cancellation Work Status: Abandoned Works Work Type: EToN 4: Minor			Version: 5 Start: 16/01/2023 09:30:00 Issued: 13/01/2023 13:36:02 Est. End: 17/01/2023		Work Desc: TM REQUIRED TO PROVIDE SAFE ACCESS TO OVERHEAD NETWORK Completion:					
Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	FROM OS ST MATTHEWS COE ACADEMY LIGHTWOOD ROAD ST3 7N3 TO JNC WITH LITTLE LANE SO THE COPSE AND OPPOSITE CROMWELL HOUSE WINDMILL HILL JNC WINDMILL CLOSE (Carriageway, Verge)	Not Known (Position)	Not Known (Depth)	0.00	0.00	Site Abandoned	16/01/2023 09:30:00			17/01/2023
Organisation: BT: OR Pole Test (0030009)										
Works Ref: PT00000000001487325 Notice Type: Registration of Non-Notifiable Works Work Status: Permanent Reinstatement - Bar Holes Work Type: EToN 4: Minor			Version: 1 Start: 09/08/2024 00:00:00 Issued: 10/08/2024 08:02:03 Est. End: 09/08/2024		Work Desc: Registration of Non-Notifiable Works Completion:					
Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	BARLASTON ROAD NEAR JCN COCKNAGE ROAD, Number of Holes: 1	Verge	Not Known (Depth)	0.00	0.00	Pole Test Reinstatement	09/08/2024		09/08/2024	
Organisation: Cyclical Maintenance (3450444)										
Works Ref: 2212110 Notice Type: Cancellation Work Status: Abandoned Works Work Type: EToN 4: Minor			Version: 3 Start: 29/09/2022 00:00:00 Issued: 29/09/2022 15:47:06 Est. End: 29/09/2022		Work Desc: Highway Road Marking Repairs - refresh slow road marker. (RMark - Worn) Completion:					
Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	On lowerside of access to property called Heather Lodge.	Not Known (Position)	Not Known (Depth)	0.00	0.00	Site Abandoned	29/09/2022			29/09/2022
Works Ref: 2212110/SG Notice Type: Cancellation Work Status: Abandoned Works Work Type: EToN 4: Minor			Version: 3 Start: 14/11/2022 00:00:00 Issued: 15/11/2022 08:22:00 Est. End: 14/11/2022		Work Desc: Highway Road Marking Repairs - refresh slow road marker. (RMark - Worn) Completion:					
Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	On lowerside of access to property called Heather Lodge.	Not Known (Position)	Not Known (Depth)	0.00	0.00	Site Abandoned	14/11/2022			14/11/2022
Works Ref: 2212110/W8 Notice Type: Works Stop Work Status: Works Stopped Work Type: EToN 4: Minor			Version: 4 Start: 03/02/2023 12:23:35 Issued: 03/02/2023 12:45:18 Est. End: 03/02/2023		Work Desc: Highway Road Marking Repairs - refresh slow road marker. (RMark - Worn) Completion: 03/02/2023					
Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	On lowerside of access to property called Heather Lodge.	Not Known (Position)	Not Known (Depth)	0.00	0.00	Site Closed (No Excavation)	03/02/2023 12:45:10			03/02/2023

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Street Works Notices**Organisation:** Highways Reactive (3450111)**Works Ref:** 2188507**Notice Type:** Cancellation**Work Status:** Abandoned Works**Work Type:** EToN 4: Minor**Version:** 5**Start:** 15/06/2020 00:00:00**Issued:** 24/12/2021 12:27:40**Est. End:** 15/06/2020**Work Desc:** Highway Drainage Investigation - Dig down in verge and replace broken 7inch salt glazed highway drainage pipe.**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Opposite gates to property called Church House approx 40 metres from jct with Lightwood Road.	Not Known (Position)	Not Known (Depth)	0.00	0.00	Site Abandoned	15/06/2020			15/06/2020

Works Ref: 2188507MW**Notice Type:** Cancellation**Work Status:** Abandoned Works**Work Type:** EToN 4: Minor**Version:** 3**Start:** 31/03/2021 00:00:00**Issued:** 30/03/2021 15:59:35**Est. End:** 02/04/2021**Work Desc:** Highway Drainage Investigation**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Opposite gates to property called Church House approx 40 metres from jct with Lightwood Road.	Not Known (Position)	Not Known (Depth)	0.00	0.00	Site Abandoned	31/03/2021			02/04/2021

Works Ref: 2207815**Notice Type:** Grant Permit**Work Status:** Works Stopped**Work Type:** EToN 4: Immediate - Emergency**Version:** 3**Start:** 23/06/2020 15:12:34**Issued:** 23/06/2020 15:43:44**Est. End:** 23/06/2020**Work Desc:** Highway Carriageway Repairs - Cat 2 pothole repairs**Completion:** 23/06/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Approximately 10m after the entrance to the property called heather lodge	Not Known (Position)	Not Known (Depth)	0.00	0.00	Site Closed	23/06/2020			23/06/2020

Works Ref: 2212108**Notice Type:** Works Stop**Work Status:** Works Stopped**Work Type:** EToN 4: Immediate - Urgent**Version:** 3**Start:** 04/08/2020 14:34:46**Issued:** 28/09/2020 10:20:30**Est. End:** 04/08/2020**Work Desc:** Highway Carriageway Repairs - Repair of multiple cat 2 potholes**Completion:** 04/08/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	In VAC to property called Heather Lodge.	Not Known (Position)	Not Known (Depth)	0.00	0.00	Site Closed	04/08/2020			04/08/2020

Works Ref: 2239347TW**Notice Type:** Works Stop**Work Status:** Works Stopped**Work Type:** EToN 4: Minor**Version:** 7**Start:** 01/07/2022 12:50:20**Issued:** 01/07/2022 15:07:36**Est. End:** 01/07/2022**Work Desc:** Highway Signage Maintenance**Completion:** 01/07/2022

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Approx 264 metres west of junction with Lightwood Road opposite pond.	Not Known (Position)	Not Known (Depth)	0.00	0.00	Site Closed	01/07/2022 15:07:26			01/07/2022

Effective: 10/09/2012 to 10/09/2026

Service: Highway Operations

Display Action Officer: No

Site: COCKNAGE ROAD (37601017)

Street Works Notices

Organisation: Highways Reactive (3450111)										
Works Ref: 2300655ERC Notice Type: Error Correction Work Status: Works Stopped Work Type: EToN 4: Immediate - Emergency			Version: 4 Start: 31/01/2023 09:07:44 Issued: 31/01/2023 09:51:12 Est. End: 31/01/2023		Work Desc: Highway Carriageway Repairs - T3. This job partsupersedes existing job number 2257817. (CW - Pothole) Completion: 31/01/2023					
Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	From junction of Barleston Rd to junction of Lightwood Road	Not Known (Position)	Not Known (Depth)	0.00	0.00	Site Closed	31/01/2023 09:32:00			31/01/2023
Works Ref: 2317648ERC Notice Type: Error Correction Work Status: Works Stopped Work Type: EToN 4: Immediate - Emergency			Version: 4 Start: 09/08/2023 10:45:15 Issued: 09/08/2023 11:37:48 Est. End: 09/08/2023		Work Desc: Highway Carriageway Repairs - T4 x 1 (CW - Pothole) Completion: 09/08/2023					
Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	From junction of Barlaston Road to junction of Lightwood Road	Not Known (Position)	Not Known (Depth)	0.00	0.00	Site Closed	09/08/2023 11:31:23			09/08/2023
Works Ref: 2328086ERC Notice Type: Error Correction Work Status: Works Stopped Work Type: EToN 4: Immediate - Emergency			Version: 7 Start: 11/01/2024 11:29:20 Issued: 12/01/2024 10:12:33 Est. End: 12/01/2024		Work Desc: Highway Carriageway Repairs - Completion: 12/01/2024					
Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	From junction of Cocknage Road to junction of Barlaston Road	Not Known (Position)	Not Known (Depth)	0.00	0.00	Site Closed	12/01/2024 10:04:01			11/01/2024
Works Ref: 2356270ERC Notice Type: Grant Permit Work Status: Works Stopped Work Type: EToN 4: Immediate - Emergency			Version: 4 Start: 01/08/2024 13:55:56 Issued: 01/08/2024 15:30:58 Est. End: 01/08/2024		Work Desc: Highway Carriageway Repairs Completion: 01/08/2024					
Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	20m prior to bridge area	Not Known (Position)	Not Known (Depth)	0.00	0.00	Site Closed	01/08/2024 14:12:00			01/08/2024
Works Ref: 2387381ERC/OOH Notice Type: Grant Permit Work Status: Works Stopped Work Type: EToN 4: Immediate - Emergency			Version: 4 Start: 28/04/2025 18:26:01 Issued: 29/04/2025 09:09:24 Est. End: 28/04/2025		Work Desc: Highway Carriageway Repairs - T3 (CW - Pothole) Completion: 28/04/2025					
Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	(carriageway)On inside of bend just up from access to Heather Lodge. Opposite severe deviation chevron boards.	Not Known (Position)	Not Known (Depth)	0.00	0.00	Site Closed	28/04/2025 18:56:00			28/04/2025

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Street Works Notices**Organisation:** Highways Reactive (3450111)**Works Ref:** 2403910ETW**Notice Type:** Error Correction**Work Status:** Works Stopped**Work Type:** EToN 4: Immediate - Emergency**Version:** 4**Start:** 10/10/2025 08:30:42**Issued:** 10/10/2025 11:36:20**Est. End:** 10/10/2025**Work Desc:** Highway Carriageway Repairs - T3This job supercedes existing job number 2387388 (CW - Pothole)**Completion:** 10/10/2025

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	(carriageway)Approximately 10 meters downhill from the property called Heather Lodge	Not Known (Position)	Not Known (Depth)	0.00	0.00	Site Closed	10/10/2025 11:20:43			10/10/2025

Works Ref: 2408434ERC**Notice Type:** Grant Permit**Work Status:** Works Stopped**Work Type:** EToN 4: Immediate - Emergency**Version:** 4**Start:** 26/11/2025 09:43:51**Issued:** 27/11/2025 08:13:37**Est. End:** 26/11/2025**Work Desc:** Highway Carriageway Repairs - T4Please make safe until permanent Repairs will be carried out under job number 2408432 (CW - Pothole)**Completion:** 26/11/2025

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	(carriageway)Approximately 30 meters east from access to property called Rose Cottage	Not Known (Position)	Not Known (Depth)	0.00	0.00	Site Closed	26/11/2025 09:59:00			26/11/2025

Works Ref: 2427419ERC**Notice Type:** Error Correction**Work Status:** Works Stopped**Work Type:** EToN 4: Immediate - Emergency**Version:** 4**Start:** 21/04/2026 12:55:03**Issued:** 21/04/2026 15:46:25**Est. End:** 21/04/2026**Work Desc:** Highway Carriageway Repairs - T4Please make good area marked Job 1 of 6 (CW - Pothole)**Completion:** 21/04/2026

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	(carriageway)20m past vac to rose cottage on the right	Not Known (Position)	Not Known (Depth)	0.00	0.00	Site Closed	21/04/2026 14:39:00			21/04/2026

Works Ref: 2427422ERC**Notice Type:** Error Correction**Work Status:** Works Stopped**Work Type:** EToN 4: Immediate - Emergency**Version:** 4**Start:** 22/04/2026 08:39:15**Issued:** 22/04/2026 12:39:03**Est. End:** 22/04/2026**Work Desc:** Highway Carriageway Repairs - T4Please make good area marked Job 2 of 6 (CW - Pothole)**Completion:** 22/04/2026

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	(carriageway)20m past vac to rose cottage on the right	Not Known (Position)	Not Known (Depth)	0.00	0.00	Site Closed	22/04/2026 12:28:43			22/04/2026

Works Ref: 30010364**Notice Type:** Cancellation**Work Status:** Abandoned Works**Work Type:** EToN 4: Minor**Version:** 3**Start:** 12/10/2023 00:00:00**Issued:** 13/10/2023 14:01:28**Est. End:** 12/10/2023**Work Desc:** Highway Drainage works - Clean and jet gully Blocked Jetting Required**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside Oakhurst	Not Known (Position)	Not Known (Depth)	0.00	0.00	Site Abandoned	12/10/2023			12/10/2023

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Street Works Notices

Organisation: Highways Reactive (3450111)										
Works Ref: 30010364SCI			Version: 5		Work Desc: Highway Drainage works - Clean and jet gully Blocked Jetting Required					
Notice Type: Error Correction			Start: 04/11/2024 10:40:40							
Work Status: Works Stopped			Issued: 04/11/2024 10:58:35							
Work Type: EToN 4: Minor			Est. End: 04/11/2024		Completion: 04/11/2024					
Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	(carriageway)Outside Oakhurst	Not Known (Position)	Not Known (Depth)	0.00	0.00	Site Closed	04/11/2024 10:52:41			04/11/2024
Works Ref: 30010364SG			Version: 5		Work Desc: Highway Drainage works - Clean and jet gully Blocked Jetting Required					
Notice Type: Cancellation			Start: 12/10/2023 00:00:00							
Work Status: Abandoned Works			Issued: 12/10/2023 15:53:31							
Work Type: EToN 4: Minor			Est. End: 12/10/2023		Completion:					
Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside Oakhurst	Not Known (Position)	Not Known (Depth)	0.00	0.00	Site Abandoned	12/10/2023			12/10/2023
Organisation: Highways Recovery (3450112)										
Works Ref: 2220368RCHRP			Version: 9		Work Desc: Highway Carriageway Repairs - Highway Improvement Works					
Notice Type: Error Correction			Start: 04/10/2024 12:38:45							
Work Status: Works Stopped			Issued: 06/12/2024 15:58:14							
Work Type: EToN 4: Major			Est. End: 04/12/2024		Completion: 04/12/2024					
Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	(carriageway)From Barlaston Rd to Lightwood Rd	Not Known (Position)	Not Known (Depth)	0.00	0.00	Site Closed	04/12/2024 16:00:00			04/12/2024
Works Ref: 2329906RCHRP			Version: 8		Work Desc: Highway Carriageway Repairs - Highway Improvement Works					
Notice Type: Inspection Auto Acknowledged			Start: 09/09/2024 09:47:32							
Work Status: Works Stopped			Issued: 25/09/2024 16:30:23							
Work Type: EToN 4: Major			Est. End: 13/09/2024		Completion: 13/09/2024					
Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Whole of USRN	Not Known (Position)	Not Known (Depth)	0.00	0.00	Site Closed	13/09/2024 16:00:00			13/09/2024
Organisation: Major/Minor Schemes (3450555)										
Works Ref: 18008749			Version: 8		Work Desc: Installing signs and posts and removing signs. 60mm excavation.					
Notice Type: Works Stop			Start: 16/05/2024 08:00:00							
Work Status: Works Stopped			Issued: 16/05/2024 13:02:31							
Work Type: EToN 4: Minor			Est. End: 16/05/2024		Completion: 16/05/2024					
Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	On the junction where Cocknage Road and Common Lane meet Lightwood Road. This permit is for the work and light head Cocknage Road. (Footway, Verge)	Not Known (Position)	Not Known (Depth)	0.00	0.00	Site Closed	16/05/2024 13:00:00			16/05/2024

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Street Works Notices**Organisation:** Preventative Maintenance (3450333)**Works Ref:** RMS26-6537-0001**Notice Type:** Works Stop**Work Status:** Works Stopped**Work Type:** EToN 4: Major**Version:** 6**Start:** 05/08/2026 09:00:00**Issued:** 11/08/2026 13:04:11**Est. End:** 11/08/2026**Work Desc:** Weather permitted mobile Highway Repair and Maintenance works. Road will only be closed for two days within the date window to allow works to take place (dates are subject to change within the date window due to weather and resource implications)**Completion:** 07/08/2026

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	[ttro] (Carriageway)USRN: 37601017 Cocknage Road- from A5005 Lightwood Road to Stoke City boundary (bend by Heather Lodge)	Not Known (Position)	Not Known (Depth)	0.00	0.00 Site Closed (No Excavation)	07/08/2026 12:00:00			11/08/2026

Works Ref: RMS26-6537-001**Notice Type:** Cancellation**Work Status:** Abandoned Works**Work Type:** EToN 4: Major**Version:** 3**Start:** 03/09/2026 07:00:00**Issued:** 13/07/2026 12:29:50**Est. End:** 11/09/2026**Work Desc:** Weather permitted mobile Highway Repair and Maintenance works. Road will only be closed for two days within the date window to allow works to take place (dates are subject to change within the date window due to weather and resource implications)**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	[ttro] (Carriageway)USRN: 37601017 Cocknage Road- from A5005 Lightwood Road to Stoke City boundary (bend by Heather Lodge)	Not Known (Position)	Not Known (Depth)	0.00	0.00 Site Abandoned	03/09/2026 07:00:00			11/09/2026

Works Ref: RMS26-6537-01**Notice Type:** Cancellation**Work Status:** Abandoned Works**Work Type:** EToN 4: Major**Version:** 5**Start:** 30/04/2026 07:00:00**Issued:** 11/06/2026 12:37:02**Est. End:** 11/05/2026**Work Desc:** Weather permitted mobile Highway Repair and Maintenance works. Road will only be closed for two days within the date window to allow works to take place (dates are subject to change within the date window due to weather and resource implications)**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	[ttro] (Carriageway)USRN 37601017 - Cocknage Road from A5005 Lightwood Road to Stoke City boundary (bend by Heather Lodge)	Not Known (Position)	Not Known (Depth)	0.00	0.00 Site Abandoned	30/04/2026 07:00:00			11/05/2026

Works Ref: SDP2406108**Notice Type:** Cancellation**Work Status:** Abandoned Works**Work Type:** EToN 4: Major**Version:** 7**Start:** 05/01/2026 00:00:00**Issued:** 17/02/2026 10:34:38**Est. End:** 07/01/2026**Work Desc:** Pre-Surface Dressing patching, to be dressed in 2026 - 331 m2**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	[ttro](carriageway)From A5005 lightwood road to stoke city boundary (bend by Heather Lodge)	Not Known (Position)	Not Known (Depth)	0.00	0.00 Site Abandoned	05/01/2026			07/01/2026

Works Ref: SDP2406108/RC**Notice Type:** Error Correction**Work Status:** Works Stopped**Work Type:** EToN 4: Major**Version:** 7**Start:** 28/04/2026 08:00:00**Issued:** 06/05/2026 15:38:25**Est. End:** 30/04/2026**Work Desc:** Pre-Surface Dressing planer patching, to be dressed in 2026 - 331 m2**Completion:** 30/04/2026

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	[ttro](carriageway)From A5005 lightwood road to stoke city boundary (bend by Heather Lodge)	Not Known (Position)	Not Known (Depth)	0.00	0.00 Site Closed	30/04/2026 16:00:00			30/04/2026

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Street Works Notices**Organisation:** Preventative Maintenance (3450333)**Works Ref:** SDPIW-2406102**Notice Type:** Cancellation**Work Status:** Abandoned Works**Work Type:** EToN 4: Minor**Version:** 5**Start:** 04/12/2025 08:13:17**Issued:** 09/01/2026 10:23:38**Est. End:** 05/12/2025**Work Desc:** Pre Surface Dressing Prep. Replace & Rebed Ironwork. In Prep for 2026 Dressing.**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	(carriageway)Approx 315m from Lightwood Road	Not Known (Position)	Not Known (Depth)	0.00	0.00 Site Abandoned	04/12/2025 08:13:17			05/12/2025

Organisation: STW Water West (9103914)**Works Ref:** 1202/000010483960**Notice Type:** Registration of Reinstatement - Full**Work Status:** Works Stopped**Work Type:** EToN 4: Minor**Version:** 4**Start:** 29/11/2012 00:00:00**Issued:** 06/12/2012 16:20:05**Est. End:** 03/12/2012**Work Desc:** Meter Reset lid Carriageway type 2 (2.5 to 10 MSA) Job in Verge (Grass)**Completion:** 29/11/2012

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	OPP. OAKHURST COCKNAGE ROAD ROUGH CLOSE STAFFORDSHIRE COUNTY COUNCIL	Verge	Up to 1.5 Metres of Cover	0.70	0.70 A Permanent Reinstatement	06/12/2012		06/12/2012	03/12/2012

Works Ref: 1202/000060105855**Notice Type:** Works Stop**Work Status:** Works Stopped**Work Type:** EToN 4: Immediate - Urgent**Version:** 2**Start:** 22/10/2013 08:40:19**Issued:** 23/10/2013 09:07:32**Est. End:** 24/10/2013**Work Desc:** Short Comm Pipe Repair 25mm Carriageway type 2 (2.5 to 10 MSA) Job in Verge (Grass)**Completion:** 22/10/2013

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	DIRECTLY OUTSIDE "BRAEMAR", APPROX 123M FROM JUNCTION WITH LIGHTWOOD ROAD	Not Known (Position)	Not Known (Depth)	0.00	0.00 Site Closed (No Excavation)	22/10/2013			24/10/2013

Works Ref: 1202/000060138506**Notice Type:** Works Stop**Work Status:** Works Stopped**Work Type:** EToN 4: Immediate - Urgent**Version:** 2**Start:** 10/11/2014 14:36:00**Issued:** 10/11/2014 15:51:22**Est. End:** 12/11/2014**Work Desc:** Short Comm Pipe Repair 2" Carriageway type 2 (2.5 to 10 MSA) Job in Verge (Grass)**Completion:** 10/11/2014

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	APPROX 135M WEST JUNCTION WITH LIGHTWOOD ROAD	Not Known (Position)	Not Known (Depth)	0.00	0.00 Site Closed (No Excavation)	10/11/2014			12/11/2014

Works Ref: 1202/000060140217**Notice Type:** Registration of Reinstatement - Full**Work Status:** Works Stopped**Work Type:** EToN 4: Immediate - Urgent**Version:** 3**Start:** 09/11/2014 09:22:00**Issued:** 09/11/2014 10:10:29**Est. End:** 11/11/2014**Work Desc:** Short Comm Pipe Repair 2" Carriageway type 2 (2.5 to 10 MSA) Job in Verge (Grass)**Completion:** 09/11/2014

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	BRAEMAR	Footpath	Up to 1.5 Metres of Cover	0.60	0.60 A Permanent Reinstatement	09/11/2014		09/11/2014	11/11/2014

Effective: 10/09/2012 to 10/09/2026

Display Action Officer: No

Service: Highway Operations

Site: COCKNAGE ROAD (37601017)

Street Works Notices**Organisation:** STW Water West (9103914)**Works Ref:** 1202/000060140295**Version:** 2**Work Desc:** Boundary box Install 25mm Carriageway type 2 (2.5 to 10 MSA) Job in Verge (Grass)**Notice Type:** Works Stop**Start:** 20/11/2014 15:15:00**Work Status:** Works Stopped**Issued:** 20/11/2014 16:04:41**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 24/11/2014**Completion:** 20/11/2014

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OPPOSITE HOUSE NAME BRAEMAR	Not Known (Position)	Not Known (Depth)	0.00	0.00	Site Closed (No Excavation)	20/11/2014			24/11/2014

Works Ref: 1202/000060152425**Version:** 3**Work Desc:** Boundary box Install 25mm Job in Verge (Grass)**Notice Type:** Registration of Reinstatement - Full**Start:** 05/05/2015 09:12:00**Work Status:** Works Stopped**Issued:** 05/05/2015 11:36:26**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 07/05/2015**Completion:** 05/05/2015

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	braemar	Verge	Up to 1.5 Metres of Cover	1.00	1.00	A Permanent Reinstatement	05/05/2015		05/05/2015	07/05/2015

Works Ref: 1202-000014207568**Version:** 7**Work Desc:** * Bbox Renew 25mm add Meter * Urgent visible leak * CARRIAGEWAY TYPE 2 (2.5 TO 10 MSA)**Notice Type:** Registration of Reinstatement - Full**Start:** 28/01/2026 11:45:07**Work Status:** Works Stopped**Issued:** 30/01/2026 16:09:47**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 30/01/2026**Completion:** 29/01/2026

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OPPOSITE BRAE MAR, Actual Depth: 1	Verge	Up to 1.5 Metres of Cover	0.90	0.60	A Permanent Reinstatement	29/01/2026		29/01/2026	30/01/2026

Works Ref: 1202-000014289062**Version:** 6**Work Desc:** * Bbox Renew 25mm add Meter-Non visible leak causing no supply**Notice Type:** Grant Permit**Start:** 01/05/2026 12:39:48**Work Status:** Works Stopped**Issued:** 01/05/2026 15:10:37**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 05/05/2026**Completion:** 01/05/2026

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Oakhurst, Actual Depth: 1	Carriageway	Up to 1.5 Metres of Cover	0.90	0.80	A Permanent Reinstatement	01/05/2026		01/05/2026	05/05/2026

Works Ref: 1202-000096119157**Version:** 5**Work Desc:** HV Boundary box Install 25mm**Notice Type:** Cancellation**Start:** 20/10/2022 07:00:00**Work Status:** Abandoned Works**Issued:** 17/10/2022 14:48:00**Work Type:** EToN 4: Minor**Est. End:** 24/10/2022**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OP BRAEMAR (Verge)	Not Known (Position)	Not Known (Depth)	0.00	0.00	Site Abandoned	20/10/2022 07:00:00			24/10/2022

Works Ref: 1202-000096119157A**Version:** 9**Work Desc:** Boundary box Install 25mm**Notice Type:** Error Correction**Start:** 23/01/2023 09:53:41**Work Status:** Works Stopped**Issued:** 25/01/2023 10:19:25**Work Type:** EToN 4: Minor**Est. End:** 25/01/2023**Completion:** 24/01/2023

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OP BRAEMAR (Verge)	Not Known (Position)	Not Known (Depth)	0.00	0.00	Site Closed (No Excavation)	24/01/2023 10:54:00			25/01/2023

Effective: 10/09/2012 to 10/09/2026		Service: Highway Operations	
Display Action Officer: No		Site: COCKNAGE ROAD (37601017)	
